

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. : SAC2401771

INV Date : 10-12-2024

Reference CD/LPC24100221/Rpa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SNG 7164L
Insured Veh. YQ 8893B
Claim No. 24/24/24/VC05/030005
Policy No. Z24VC05022226
Accident Date 10/10/2024
Inspection Date 21/10/2024

Description	Amount
Third Party Express Settlement	450.00
Sub-Total	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CD/LPC24100221/Rpa3q2
300 BEACH ROAD	Date:	10/12/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	YQ 8893B	Veh. Inspected	SNG 7164L
Policy No.	Z24VC05022226	Coverage	0
Claim No.	24/24/24/VC05/030005	Excess	\$0.00
Assign From	ERIC WOO	Assign Date	10/10/2024

2. Vehicle Details

Make & Model	TOYOTA COROLLA ALTIS	C.C	1598
Engine No.	1ZR0J09994	Year of Reg.	29/08/2022
Chassis No.	MR2BE3BEX00019782	Colour	GREY
Odometer	47626 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/55 R16	BRIGESTONE	6
L/H Front Tyre	205/55 R16	BRIGESTONE	6
R/H Rear Tyre	205/55 R16	BRIGESTONE	6
L/H Rear Tyre	205/55 R16	BRIGESTONE	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/10/2024	Inspection Date	21/10/2024
Survey held at	48 TOH GUAN ROAD EAST #02-146/147 S 608586		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNG 7164L

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	Rear Bumper	DEFORMED	\$1,150.00	\$1,150.00
1	Rear Bumper Retainer RH	NOT NECESSARY	\$100.00	\$0.00
1	Rear Bumper Retainer LH	NOT NECESSARY	\$100.00	\$0.00
1	Reverse Sensor RH	NOT NECESSARY	\$300.00	\$0.00
1	Reverse Sensor LH	NOT NECESSARY	\$300.00	\$0.00
1	Rear Reinforcement	SERVICEABLE	\$650.00	\$0.00
2	Tail Lamp Special Clip	NOT NECESSARY	\$20.00	\$0.00
1	Bootlid Lamp RH	NOT NECESSARY	\$780.00	\$0.00
1	Bootlid Lamp LH	NOT NECESSARY	\$780.00	\$0.00
1	Bootlid	BENT	\$1,500.00	\$1,500.00
1	Bootlid outer Chrome Garnish	SERVICEABLE	\$300.00	\$0.00
1	Bootlid Toyota Emblem	NECESSARY	\$100.00	\$100.00
1	Bootlid Corolla Emblem	NECESSARY	\$100.00	\$100.00
1	Bootlid Altis Emblem	NECESSARY	\$100.00	\$100.00
	LESS 20.00 / 25.00% DISCOUNT		(\$1,256.00)	(\$737.50)
			\$5,024.00	\$2,212.50
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	Rear Number Plate w Casing	NOT NECESSARY	\$40.00	\$0.00
10	Rear Number Clips	NECESSARY	\$30.00	\$30.00
			\$70.00	\$30.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	Repair and Replace Affected Accident Parts		\$750.00	\$400.00
	Spray Paint (Bootlid, Rear Bumper, Rear Reinforcement)		\$750.00	\$400.00
	Rust Proofing		\$80.00	\$40.00
	Remove and Refit Reverse Sensors		\$80.00	\$40.00
	Check and Rectify Electrical Wiring		\$30.00	\$0.00
			\$1,690.00	\$880.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

GRAND TOTAL		\$6,784.00	\$3,122.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$2,500.00
Report Ref No: CD/LPC24100221/Rpa3q2			

MARKET VALUE: \$123,000.00(EST) LESS LTA REBATE: \$83,551.00(EST) = NETT VALUE :\$39,449.00(EST)

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SNG 7164L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 7164L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 7164L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 7164L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 7164L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 7164L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 7164L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 7164L

