

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TP 111
Yan.

EMBRACE FUNERAL SERVICES PTE LTD
624B PUNGGOL CENTRAL #13-310 PUNGGOL
SPECTRA
SINGAPORE 822624

TAX INVOICE

Repair Code : CLM18409

Date in : 14/10/2024

Vehicle Num. : GBE8737E

Model : TOYOTA HIACE 3.0 A

Chassis/Eng# : KDH2010189568/1KD2589507

Contact : 96921100 83395163

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>cut</i>	1	836.70	✓ 836.70
FRONT BUMPER RH SIDE RETAINER <i>new</i>	1	154.80	+ 154.80
FRONT CORNER PANEL <i>Rego</i>	1	290.50	+ 290.50
FRONT RH DOOR <i>Derbit</i>	1	2904.10	2065 2904.10
FRONT RH DOOR CHECKER	1	96.50	+ 96.50
FRONT RH DOOR HINGE (LOWER)	1	199.40	+ 199.40
FRONT RH DOOR HINGE (TOP)	1	199.40	+ 199.40
FRONT RH DOOR SIDE MIRROR ASSY <i>new</i>	1	1507.50	1310 1507.50
FRONT RH DOOR WEATHER STRIP <i>new</i>	1	249.40	+ 249.40
FRONT RH HEADLAMP <i>cut</i>	1	1264.90	✓ 1,264.90
Subtotal before discount			7,703.20
Percentage discount 25%			1,925.80
Sub-total 1			5,777.40
FRONT BUMPER CLIPS - SET <i>new</i>	1	50.00	30 50.00
FRONT RH DOOR 3D ART WORK STICKER <i>new</i>	1	450.00	20 450.00
FRONT RH DOOR COMPANY DETAIL STICKER <i>new</i>	1	25.00	✓ 25.00
FRONT RH DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	+ 50.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

EMBRACE FUNERAL SERVICES PTE LTD
 624B PUNGGOL CENTRAL #13-310 PUNGGOL
 SPECTRA
 SINGAPORE 822624

Contact : 96921100 83395163

TAX INVOICE

Repair Code : CLM18409

Date in : 14/10/2024

Vehicle Num. : GBE8737E

Model : TOYOTA HIACE 3.0 A

Chassis/Eng# : KDH2010189568/1KD2589507

	Subtotal before discount	575.00
Percentage discount 0%		0.00
	Sub-total 2	575.00
	Parts-total	6,352.40

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	2,180.00
Parts & Labour Total	8,532.40

1020
 30 80.00
 60 120.00
 400. 1,000.00
 500 900.00
 30 80.00

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Admin L
 L/S 14/10/24.
 04 Days
 Total 5382.45
 L/S 4.3K
 4.3K