

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CS/AIG24100223/TVP3E2**Date:** 23/06/2025REFERENCE

Insured/Claimant:	SIAW TUNG YENG	Policy No:	1800111858	
Date of Loss:	11/10/2024	Nature of Claim:	OD	Claim No: 7081947724SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF1999B		
Make & Model:	AUDI TT, 1.8 COUPE TFSI S-TRONIC (A)	Engine No:	CJS258422
Reg. Date:	28/09/2018 (Man. Year: 2018)	Chassis No:	TRUZZZFV8J1017182
Colour:	White	Odometer:	61348 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$110,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	102,408.40	38,404.72	64,003.68	62.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	32,332.00	17,722.00	14,610.00	45.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	134,740.40	56,126.72	78,613.68	58.34
- Excess (\$\$)	1,200.00	1,200.00	0.00	0.00
(\$\$)	133,540.40	54,926.72	78,613.68	58.87
+ GST 9.00/9.00% (\$\$)	12,018.64	4,943.40	7,075.24	58.87
Nett Amount (\$\$)	145,559.04	59,870.12	85,688.92	58.87

INSPECTION

Date of Assignment:	14/10/2024	
Date Inspected:	15/10/2024	Inspected At: 24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	19.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Scratched	2,989.00 FS	*2,391.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	543.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	140.00 FS	*- FS
4	2		*FRONT BUMPER SECURING STRIP LH / RH	Not Necessary	108.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	202.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Deformed	196.00 FS	*156.80 FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	272.00 FS	*- FS
8	1		*RADIATOR GRILLE	Not Necessary	1,679.00 FS	*- FS
9	1		*FRONT PARKING AID SENSOR	Not Necessary	286.00 FS	*- FS
10	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	11.00 FS	*- FS
11	1		*FRONT BUMPER GUIDE SECTION	Not Necessary	49.00 FS	*- FS
12	1		*LED HEADLIGHT - RH	Not Necessary	9,471.00 FS	*- FS
13	1		*LIFT CYLINDER - RH (NPA)	Not Necessary	0.00 FS	*- FS
14	1		*LIFT CYLINDER HOSE	Not Necessary	97.00 FS	*- FS
15	1		*FRONT FENDER - RH	Repair	1,417.00 FS	*- FS
16	1		*FRONT FENDER ATTACHMENT PARTS - RH	Not Necessary	47.00 FS	*- FS
17	1		*FRONT FENDER BRACE - RH	Not Necessary	144.00 FS	*- FS
18	1		*FRONT FENDER BRACKET - RH UPPER CENTRE	Not Necessary	55.00 FS	*- FS
19	1		*FRONT FENDER BRACKET - RH LOWER	Not Necessary	56.00 FS	*- FS
20	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	53.00 FS	*- FS
21	1		*FRONT FENDER BRACKET - RH LOWER	Not Necessary	56.00 FS	*- FS
22	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	83.00 FS	*- FS
23	1		*FRONT FENDER BRACKET - RH LOWER	Not Necessary	63.00 FS	*- FS
24	1		*FRONT FENDER SEAL - RH	Not Necessary	47.00 FS	*- FS
25	1		*FRONT WHEEL HOUSING LINER SEAL - RH	Not Necessary	47.00 FS	*- FS
26	1		*FRONT WHEEL HOUSING LINER - RH	Cut	206.00 FS	*164.40 FS
27	1		*WHEEL HOUSING LINER ATTACHMENT PARTS - RH	Not Necessary	125.00 FS	*- FS
28	1		*FRONT WHEEL SPOILER - RH	Scratched	141.00 FS	*112.80 FS
29	1		*AUDI EMBLEM	Not Necessary	162.00 FS	*- FS
30	1		*A-PILLAR FRAME	Repair	3,611.00 FS	*- FS
31	1		*SILL TRIM STRIP - RH OUTER	Not Necessary	316.00 FS	*- FS
32	1		*SIDE MEMBER TRIM - RH	Cracked	818.00 FS	*654.00 FS
33	1		*SIDE MEMBER TRIM ATTACHMENT PARTS - RH	Necessary	314.00 FS	*250.80 FS
34	1		*SIDE MEMBER TRIM ADHESIVE TAPES - RH	Necessary	260.40 FS	*260.40 FS
35	1		*SIDE MEMBER TRIM BRACKET - RH	Necessary	25.00 FS	*19.84 FS
36	1		*REAR WHEEL SPOILER - RH REAR	Not Necessary	44.00 FS	*- FS
37	1		*JACKING POINT BRACKET - RH	Not Necessary	81.00 FS	*- FS
38	1		*UNDERBODY TRIM	Not Necessary	303.00 FS	*- FS
39	1		*NOISE INSULATION	Not Necessary	292.00 FS	*- FS
40	1		*NOISE INSULATION FIXING PARTS	Not Necessary	54.00 FS	*- FS
41	1		*UNDERBODY TRIM - RH OUTER	Not Necessary	155.00 FS	*- FS
42	1		*UNDERBODY TRIM - RH REAR	Not Necessary	94.00 FS	*- FS
43	1		*CENTRE SILENCER	Not Necessary	1,178.00 FS	*- FS
44	1		*CENTRE SILENCER DUAL CLIP	Not Necessary	70.00 FS	*- FS
45	1		*CENTRE SILENCER DUAL CLIP	Not Necessary	70.00 FS	*- FS
46	1		*CENTRE SILENCER RETAINER	Not Necessary	51.00 FS	*- FS
47	1		*REAR SILENCER	Not Necessary	1,736.00 FS	*- FS
48	2		*REAR SILENCER BRACKET - REAR	Not Necessary	107.00 FS	*- FS
49	2		*REAR SILENCER CHROME TRIM - LH / RH	Not Necessary	322.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*STEERING WHEEL	Not Necessary	2,971.00 FS	*- FS
51	1		*STEERING WHEEL AIRBAG UNIT	Not Necessary	4,597.00 FS	*- FS
52	1		*ROOF LINER	Necessary	1,734.00 FS	*1,387.20 FS
53	1		*ROOF AIRBAG	Activated	2,323.00 FS	*1,858.40 FS
54	1		*A-PILLAR TRIM - RH UPPER	Deformed	264.00 FS	*210.80 FS
55	1		*C-PILLAR TRIM - RH	Deformed	295.00 FS	*236.00 FS
56	1		*DRIVER SEAT BACK LEATHER	Torn	4,707.00 FS	*3,765.60 FS
57	1		*DRIVER SEAT PADDING	Not Necessary	533.00 FS	*- FS
58	1		*DRIVER SEAT REST LEATHER	Not Necessary	3,044.00 FS	*- FS
59	1		*DROVER SEAT REST PADDING - CENTER	Not Necessary	533.00 FS	*- FS
60	2		*DRIVER SEAT REST PADDING - LH / RH	Not Necessary	354.00 FS	*- FS
61	1		*SIDE AIRBAG UNIT - RH	Activated	1,900.00 FS	*1,520.00 FS
62	1		*SIDE AIRBAG UNIT WIRE HARNESS - RH	Not Necessary	238.00 FS	*- FS
63	1		*SEAT BELT FITTINGS - RH	Not Necessary	80.00 FS	*- FS
64	1		*TRIM PLATE FOR SEAT BELT GUIDE - RH	Not Necessary	41.00 FS	*- FS
65	1		*FUEL TANK	Not Necessary	4,404.00 FS	*- FS
66	3		*ALUMINIUM RIM BOTH RHS AND FRONT LHS	Broken	6,369.00 FS	*5,095.20 FS
67	3		*ALUMINIUM RIM RUBBER VALVE	Necessary	9.00 FS	*7.20 FS
68	1		*FRONT WISHBONE - RH	Bent	1,053.00 FS	*842.40 FS
69	1		*STABILIZER, COMPLETE	Not Necessary	479.00 FS	*- FS
70	1		*FRONT WHEEL BEARING HOUSING - RH	Bent	1,196.00 FS	*956.80 FS
71	1		*FRONT WHEEL HUB - RH	Bent	593.00 FS	*474.00 FS
72	1		*FRONT GUIDE JOINT - RH	Bent	225.00 FS	*179.60 FS
73	1		*FRONT RETAINING PLATE - RH	Not Necessary	39.00 FS	*- FS
74	1		*FRONT COUPLING ROD - RH	Bent	112.00 FS	*89.60 FS
75	1		*AIR GUIDE - RH	Not Necessary	56.00 FS	*- FS
76	1		*FRONT SHOCK ABSORBER - RH	Bent	437.00 FS	*349.20 FS
77	1		*FRONT DRIVESHAFT - RH	Bent	1,615.00 FS	*1,292.00 FS
78	1		*FRONT WHEEL SPEED SENSOR WIRE HARNESS - RH	Not Necessary	256.00 FS	*- FS
79	1		*FRONT BRAKE HOSE - RH	Not Necessary	97.00 FS	*- FS
80	1		*STEERING RACK	Not Necessary	6,431.00 FS	*- FS
81	1		*STEERING TIE ROD - LH / RH	O/S Broken / N/S Not Necessary	372.00 FS	*148.80 FS
82	1		*STEERING TIE ROD END - LH / RJ	O/S Broken / N/S Not Necessary	372.00 FS	*148.80 FS
83	1		*FRONT SUBFRAME	Bent	1,309.00 FS	*1,047.20 FS
84	1		*SET SUBFRAME BUSHES - UPPER / LOWER	Bent	189.00 FS	*150.80 FS
85	2		*REAR TRACK ROD	Bent	281.00 FS	*224.80 FS
86	1		*REAR COUPLING ROD	Bent	77.00 FS	*61.36 FS
87	1		*ANTI-ROLL BAR	Not Necessary	278.00 FS	*- FS
88	1		*TRACK ROD BRACKET - RH	Bent	168.00 FS	*134.40 FS
89	1		*REAR AXLE GUIDE - RH	Bent	356.00 FS	*284.80 FS
90	1		*REAR WISHBONE - RH	Bent	308.00 FS	*246.40 FS
91	1		*REAR WISHBONE - RH UPPER	Bent	308.00 FS	*246.40 FS
92	1		*REAR WHEEL BEARING HOUSING - RH	Bent	771.00 FS	*616.40 FS
93	1		*REAR WHEEL HUB - RH	Bent	593.00 FS	*474.00 FS
94	1		*STONE CHIP GUARD - RH	Not Necessary	12.00 FS	*- FS
95	1		*REAR SUPPORT FRAME	Bent	1,803.00 FS	*1,442.40 FS
96	2		*REAR SHOCK ABSORBER	Not Necessary	729.00 FS	*- FS
97	1		*REAR WHEEL SPEED SENSOR WIRE HARNESS - RH	Not Necessary	256.00 FS	*- FS
98	1		*AIR BAG CONTROL UNIT	Necessary	2,054.00 FS	*1,643.20 FS
99	1		*DATA TAG	Not Necessary	567.00 FS	*- FS
100	2		*FRONT SEAT BELT - LH / RH	Activated	2,600.00 FS	*2,080.00 FS
101	2		*REAR SEAT BELT - LH / RH	Not Necessary	1,344.00 FS	*- FS
102	2		*FRONT SEAT BELT ADJUSTER - LH / RH	Not Necessary	413.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
103	1		*FRONT NO PLATE	Not Necessary	1,500.00 FS	*- FS
104	1		*FRONT TYRE - RHS	Cut	320.00 FS	*320.00 FS
105	1		*REAR TYRE - RHS	Cut	320.00 FS	*320.00 FS
106	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
107	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
108	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
109	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
110	1		*SUNDRIES	Necessary	1,500.00 FS	*786.72 FS
111	1		*SIDE PANEL TRIM RHS (SUPPLEMENTARY)	Deformed	1,041.00 FS	*832.80 FS
112	1		*SIDE PANEL TRIM LHS (SUPPLEMENTARY)	Deformed	1,041.00 FS	*832.80 FS
113	1		*TRIM PLATE FOR SEAT BELT GUIDE LHS (SUPPLEMENTARY)	Deformed	31.00 FS	*24.24 FS
114	1		*TRIM PLATE FOR SEAT BELT GUIDE RHS (SUPPLEMENTARY)	Deformed	31.00 FS	*24.24 FS
115	1		*BRAKE CALIPER CARRIER RHS FRONT (SUPPLEMENTARY)	Bent	319.00 FS	*255.20 FS
116	1		*BRAKE DISC RHS FRONT (SUPPLEMENTARY)	Bent	232.00 FS	*185.60 FS
117	1		*WHEEL HOUSING LINER RHS REAR (SUPPLEMENTARY)	Deformed	289.00 FS	*231.20 FS
118	1		*CALIPER BRACKET RHS REAR (SUPPLEMENTARY)	Bent	237.00 FS	*189.20 FS
119	2		*GUIDE PIN (SUPPLEMENTARY)	Bent	164.00 FS	*130.72 FS
120	1		*SET GUIDE BUSHES (SUPPLEMENTARY)	Distorted	46.00 FS	*36.40 FS
121	1		*BATTERY CENTRAL PROTECTION (SUPPLEMENTARY)	Bent	627.00 FS	*501.20 FS
122	1		*SEAT BELT GUIDE RHS (SUPPLEMENTARY)	Deformed	122.00 FS	*97.20 FS
123	1		*SEAT BELT GUIDE LHS (SUPPLEMENTARY)	Deformed	122.00 FS	*97.20 FS
124	2		*REAR SEAT BELT - LH / RH (SUPPLEMENTARY)	Activated	2,600.00 FS	*2,080.00 FS
125	1		*C-PILLAR TRIM - LH (SUPPLEMENTARY)	Deformed	295.00 FS	*236.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **102,408.40** **38,404.72**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER REAR PARKING AID	New	280.00	280.00
3	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	0.00
4	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND INSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR	New	280.00	0.00
5	TO REMOVE CENTRE CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW FRONTAL AIRBAG, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING AND BOTH CURTAIN AIRBAGS	New	3,600.00	3,600.00
6	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS	New	1,800.00	0.00
7	TO RENEW RHS FRONT SEAT CUSHION ASSY	New	880.00	880.00
8	TO REMOVE AND REINSTALL REAR BUMPER. TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, RHS SILL PANEL AND RHS HEADLIGHT. TO CUT OUT AND WELD RHS SILL PANEL. TO REPAIR RHS FRONT DOOR AND RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,200.00	2,000.00
9	TO RESPRAY FRONT AND REAR BUMPER, BONNET, RHS FRONT AND REAR FENDER, RHS FRONT DOOR, RHS SILL PANEL, RHS SILL PANEL, RHS SILL PANEL TRIM, ROOF CHANNEL, DOOR ENTRANCE AND DRAIN CHANNEL	New	8,400.00	2,750.00
10	TO REMOVE AND RENEW CENTER AND REAR EXHAUST SILENCERS. TO REALIGN REAR EXHAUST SILENCER	New	480.00	0.00
11	TO REMOVE AND RENEW FUEL TANK ASSY	New	800.00	0.00
12	TO RENEW RHS FRONT AND REAR RIM WITH TYRE AND CARRY OUT WHEEL ALIGNMENT	New	1,040.00	1,040.00
13	TO REMOVE AND REINSTALL FRONT SUSPENSION. INSPECT FOR DAMAGE AND RENEW ACCORDINGLY	New	3,200.00	3,200.00
14	TO REMOVE AND REINSTALL FRONT SUSPENSION. INSPECT FOR DAMAGE AND RENEW ACCORDINGLY	New	3,200.00	3,200.00
15	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (\$\$)			32,332.00	17,722.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >