

ESTIMATE

14/10/2024

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Vehicle No: SMR2915Z
Vehicle Model: HONDA VEZEL
Est No: CBMQ24100128
Claims ref:
Accident Date: 09/10/24
In Charge: KEONG
Remarks:

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg
Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-008864-2

No	Description	Qty	U. Price	Amounts S\$
LIST ITEMS:				
1	REAR BOOT <i>bt</i>	1	PC \$ 1,137.60	\$ 1,137.60 <i>1086.10</i>
2	REAR BOOT EMBLEM "VEZEL" <i>m</i>	1	PC \$ 63.70	\$ 63.70
3	REAR BOOT LAMP LH <i>*cm</i>	1	PC \$ 287.30	\$ 287.30
4	REAR BOOT WINDSCREEN MOULDING <i>m</i>	4	PC \$ 39.60	\$ 158.40 <i>110</i>
5	REAR BOOT LOCK <i>x su</i>	1	PC \$ 183.70	\$ 183.70 <i>X</i>
6	REAR BOOT RUBBER <i>m</i>	1	PC \$ 135.10	\$ 135.10
7	REAR LAMP LH <i>*cm</i>	1	PC \$ 523.90	\$ 523.90 <i>495.20</i>
8	REAR BUMPER SIDE LH <i>su</i>	1	PC \$ 176.30	\$ 176.30
9	REAR BUMPER <i>de</i>	1	PC \$ 593.10	\$ 593.10 <i>566</i>
10	REAR BUMPER REFLECTOR LH <i>su</i>	1	PC \$ 178.50	\$ 178.50 <i>151</i>
11	REAR BUMPER CLIPS <i>m</i>	10	PC \$ 4.10	\$ 41.00
12	REAR END PANEL <i>?bt</i>	1	PC \$ 496.50	\$ 496.50 <i>470.20</i>
13	REAR END PANEL TRIM <i>?de</i>	1	PC \$ 112.30	\$ 112.30 <i>98.40</i>
14	REAR KEYLESS SENSOR <i>?cm</i>	1	PC \$ 196.50	\$ 196.50 <i>185.40</i>
15	REAR BUZZER <i>?cm</i>	1	PC \$ 118.20	\$ 118.20 <i>110</i>
16	REAR UNDER COVER <i>de</i>	1	PC \$ 296.50	\$ 296.50 <i>273.20</i>
17	REAR SPARE TYRE PANEL - REPAIR	1	PC	\$ -
18	REAR FENDER LH - REPAIR	1	PC	\$ -
19	REAR CHASSIS MEMBER - REPAIR	1	PC	\$ -

LIST TOTAL S\$

20% DISCOUNT S\$

4248.90

20%

3399.12

\$ 4,698.60

\$ (939.72)

\$ 3,758.88

SPECIAL NET ITEMS:

1	REAR BUMPER SENSOR <i>su</i>	<i>220</i>	1	PC \$ 220.00	\$ 220.00
2	NUMBER PLATE <i>X</i>		1	PC \$ 40.00	\$ 40.00 <i>X</i>

SPECIAL NET TOTAL S\$

\$ 260.00

LABOUR CHARGE:

- 1 TO CUT & WELD REAR END PANEL, TO REPAIR REAR FENDER LH, REAR FLOOR PANEL, REAR CHASSIS MEMBER, TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS

500 900-
\$ 1,140.00

* This is a computer generated letter and does not need a signature.

bizSAFE

ESTIMATE

14/10/2024

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Vehicle No: SMR2915Z
Vehicle Model: HONDA VEZEL
Est No: CBMQ24100128
Claims ref:
Accident Date: 09/10/24
In Charge: KEONG
Remarks:

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No	Description	Qty	U. Price	Amounts S\$
2	TO SPRAY AFFECTED AREAS, REAR BOOT, END PANEL, SPARE TYRE PANEL, REAR FENDER L+R, REAR BUMPER & AFFECTED AREAS			350 700 \$ 1,000.00
3	TO REMOVE & REFIX REAR WINDSCREEN GLASS			\$ 180.00 120
4	TO REMOVE & REFIX REAR BOOT MECHANISM, CHECK & TEST WIPER MOTOR & CENTRE LOCKING SYSTEM			\$ 100.00 60
5	TO INSTALL REVERSE SENSOR & CHECK WATER SEEPAGE		1880	\$ 60.00 40
6	TO RUST PROOF AFFECTED AREAS			\$ 80.00 60
TOTAL LABOUR COST S\$				\$ 2,560.00

AMOUNT S\$ \$ 6,578.88
GST @ 9% \$ 592.10
AMOUNT DUE S\$ \$ 7,170.98

Customer's Signature

MOVA AUTOMOTIVE PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

3399.12
220.00
1880.00
5499.12
269
4399.29
48- \$4,400/7days
Reg after year

Panel
Hf 900 100 68
4 days + 3 = 7 days
48
21/10/24