



SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION		
INCIDENT NO.: /20240620/0835	LOCATION OF FIRE: Along Pan Island Expressway (PIE), Toward Tuas Near Lamp Post 1839 Singapore	
FIRE REPORTED ON: 20 June 2024		
TIME OF CALL: 16:44:34 hrs		
STATION COVERAGE: Jurong Fire Station		
2. INCIDENT INFORMATION		
FIRE INVOLVED: The engine compartment of a Nissan lorry (GBH650H).		
METHOD OF EXTINGUISHMENT: By SCDF crew using hose reel jets from fire appliances.		
PROBABLE CAUSE OF FIRE: Accidental (Overheating/electrical origin at the engine compartment).		
DAMAGE OBSERVED*: As a result of the fire, the engine compartment of the lorry was damaged. Other parts of the lorry sustained heat, smoke and water damage.		
3. FATALITY/INJURY INFORMATION		
NAME	NRIC/FIN	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL
REPORT ISSUED BY: NICK LI KEJING for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE		

**This is based on observations made by the fire investigator incidental to his/her investigation to determine the cause and origin of the fire, and is not to be taken as an exhaustive list of damage caused by the fire.*

This is a computer generated report. No signature is required.