

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CD/LPC 24100231/4003

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GAL 62085

at Workshop m/s

Car Smith

of

Insured:

GAG 3805

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$74k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

C118W

Date:

Person Contacted:

Vehicle: IN / OUT

21/11/13 17911

Date / Time

Action / Instruction

dep 10/10/13

22/10/13

2/5 \$3200 : inform Alex

Veh No:

GAL 62085

Yr Regn:

24/11/13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Toyota hiace DX 2.0c.c 1998

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

58857

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

TRM 2000341235

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195-12.5

R:

Scopie

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Triangle

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

11/10/124

D.O.I.

16/10/124

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

CARSMITH PRIVATE LIMITED
PREMIER@8KAKI BUKIT AVE 4 #04-35 SINGAPORE415875
 Tel: 9091 0000/ Email: claims@carsmith.biz

*Not Authorized
as
Morang*

VEHICLE NO: GBL6208S
 MAKE & MODEL: TOYOTA HIACE
 DOA: 11.10.2024
 CLAIM TYPE: TP CLAIM

*16/10/24
 d/s # 3200
 5 days
 telephone report*

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
TAILGATE	1	\$ 1,890.00	20/200 -
TAILGATE RUBBER TOP GARNISH	1	\$ 102.70	11 X
TAILGATE RUBBER	1	\$ 328.50	11 X
TAILGATE LOCK	1	\$ 285.10	11 X
TAILGATE HINGE	2	\$ 190.50	11 X
TAILGATE ABSORBER	2	\$ 590.00	11 X
TAILGATE CENTER GARNISH	1	\$ 186.50	SVLX
TAILGATE INNER BOARD	1	\$ 335.20	11 X
TAILGATE LOCK ACTUATOR	1	\$ 430.60	11 X
TAILGATE EMBLEM LOGO	1	\$ 108.00	11 X
TAILGATE WINDSCREEN MOULDING	1	\$ 218.50	11 X 25-10
TAILGATE WINDSCREEN	1	\$ 1,250.00	11 X
TAILGATE STOPPER	2	\$ 80.00	11 X
REAR END PANEL INNER	1	\$ 912.70	R X
REAR END PANEL OUTER	1	\$ 486.50	20/200 -
REAR FLOOR BOARD PANEL	1	\$ 2,381.40	R X
REAR BUMPER	1	\$ 698.00	20/200 -
REAR BUMPER SIDE RETAINER	2	\$ 161.60	11 X
REAR BUMPER LOWER SUPPORT BRACKET	4	\$ 244.80	20/200 - 96
REAR TAILLAMP RH	1	\$ 382.20	11 X
REAR TAILLAMP GARNISH RH	1	\$ 159.50	11 X
REAR TAILLAMP PANEL RH	1	\$ 322.70	R X
REAR TAILLAMP BRACKET RH	1	\$ 118.00	11 X
REAR TAILLAMP LH	1	\$ 382.20	11 X
REAR TAILLAMP GARNISH LH	1	\$ 159.50	11 X
REAR TAILLAMP PANEL LH	1	\$ 322.70	R X
REAR TAILLAMP BRACKET LH	1	\$ 118.00	11 X
REAR TAILLAMP LOWER GARNISH RETAINER	1	\$ 351.00	20/200 -
REAR FENDER LH	1	\$ 81.00	11 X
REAR DOOR RAILING LH	1	\$ 2,745.00	11 X
		\$ 368.00	11 X
		\$ 16,390.40	
		\$ 1,639.04	
		\$ 14,751.36	

LESS 25%
 SUB TOTAL

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR BUMPER CLIP	1 SET	\$ 50.00	11 X
REAR NUMBER PLATE	1 SET	\$ 80.00	11 X
TAILGATE STICKER '70KM/H'	1	\$ 45.00	11 X
REVERSE SENSOR	1 SET	\$ 480.00	11 X
REVERSE CAMERA	1 SET	\$ 480.00	11 X
JOINT SEALANT	1	\$ 120.00	11 X
		\$ 1,255.00	

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK ACCIDENT AFFECTED AREA WIRING AND LIGHTING SYSTEM	1	\$ 300.00	20

REMOVE AND ^{refit} RENEW REAR REVERSE SENSOR	1	\$ 120.00	30
REMOVE AND REFIT ACCIDENT AFFECTED AREA LINING, TRIM AND GARNISH	1	\$ 300.00	11 X
PANEL BEATING ON REAR ACCIDENT AFFECTED AREAS AND RENEW DAMAGE PARTS	1	\$ 1,600.00	600
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	1	\$ 1,600.00	580
APPLY ANTI RUST ON ACCIDENT AFFECTED AREAS	1	\$ 100.00	50

SUB TOTAL \$ 4,020.00

GRAND TOTAL \$ 20,026.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 3606.6
252
2704.55
40
1280
4024.55
202
3219.