



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details				
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987		S1000026 / ICECICS	Mr Bek Yong Huat 60 Bayshore Road #25-01 Singapore 469982 Mobile: 91818376				
		Document No. 0					
		Document Date 14/10/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZGE20R	HPXNP S6	09/09/2016	SGR3828G	0	33852	79/DS/SGR3828G
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDGG20W70J005149		2ZR1832142	60	Ong Wen Hong	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY TP INS:ECICS TP VEH:SMF3550Z DATE OF ACC:12/10/2024 NUMBER OF REPAIR DAYS: SURVEY BY:				50	100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				100	120.00
3	B	BP-LAB2 TO REPLACE AND REPAIR ACCIDENT DAMAGED P ARTS				1584	2880.00
4	B	BP-RES2 TO RESPRAY ALL ACCIDENT AFFECTED AREAS				1812	1888.00
5	B	BP-LAB2 TO CHECK WIRING SYSTEM					97.92
6	B	BP-LAB2 TO DRILL HOLE AND INSTALL REVERSE SENSOR					144.00
7	B	BP-LAB2 TO REMOVE AND TRANSFER BOOT COMPONENT TO NEW BOOT					288.00
8	B	BP-ECU2 TO RESET ECU AND REPROGRAMME					144.00
9	B	BP-WS2 TO REMOVE AND INSTALL REAR WINDSCREEN					369.60
10	S	BP-SUBLET TO SUPPLY SOLAR FILM FOR REAR WINDSCREEN					480.00
11	1	T52159-68907 PLATE,RR BUMPER	1.00	911.60	30.00		638.12
12	2	T52462-68010 PAD, RR BUMPER, RH	2.00	7.50	30.00		10.50
13	3	T52462-68020 PAD, RR BUMPER, RH	2.00	7.50	30.00		10.50
14	4	S52161-0K040 PIECE, RR BUMPER	8.00	5.80	30.00		32.48
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature	Charge Summary			Total	
		Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others			Less Amount Due	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. : 6631 1188

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE

Account Details		Account No.	Customer Details	
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987		S1000026 / ICECICS	Mr Bek Yong Huat 60 Bayshore Road #25-01 Singapore 469982	
		Document No. 0		
		Document Date 14/10/2024	Mobile: 91818376	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZGE20R	HPXNP S6	09/09/2016	SGR3828G	0	33852	79/DS/SGR3828G

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDGG20W70J005149	2ZR1832142	60	Ong Wen Hong	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
15	5	T52575-68020 RETAINER, RR BUMPER	1.00	70.20	30.00	49.14
16	6	T52155-68030 SUPPORT, RR BUMPER	1.00	149.10	30.00	104.37
17	7	T52576-68020 RETAINER, RR BUMPER	1.00	70.20	30.00	49.14
18	8	T52156-68030 SUPPORT, RR BUMPER	1.00	149.10	30.00	104.37
19	9	T58307-68031 PANEL SUB-ASSY, BODY	1.00	817.70	30.00	572.39
20	0	T67935-68020 B0 PLATE, BACK DOOR	1.00	413.40	30.00	289.38
21	1	T67005-68041 PANEL SUB-ASSY, BACK	1.00	2263.80	30.00	1584.66
22	2	T67881-68030 WEATHERSTRIP, BACK	1.00	465.30	30.00	325.71
23	3	T68105-68071 GLASS SUB-ASSY, BACK	1.00	1480.50	30.00	1036.35
24	4	T69350-28151 LOCK ASSY, BACK DOOR	1.00	571.50	30.00	400.05
25	5	T90975-02086 EMBLEM, SYMBOL	1.00	73.50	30.00	51.45
26	6	T75444-68010 PLATE, LUGGAGE COMPT	1.00	56.90	30.00	39.83
27	7	T89997-30070 ANTENNA, ELECTRICAL	1.00	266.20	30.00	186.34
28	8	T21000-20 SIKI 182010 SIKI TACK GO! (BLA	2.00	108.00	30.00	151.20
29	9	T21000-22 SIKI 207. G+P ADHESIVE PRIMER	1.00	200.00	30.00	140.00

*Steve (LKK)
13/5/25, 10.00*

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			12,287.50
	Please acknowledge receipt of vehicle	Parts 5,775.98	GST 9.00% 1,105.88
		Labour 6,031.52	
		Sublet 480.00	
		Lubrication/Fluid 0.00	Less 0.00
		Others 0.00	Amount Due 13,393.38

5 days

Customer Copy