



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987	S1000026 / ICECICS	Mr Bek Yong Huat 60 Bayshore Road #25-01 Singapore 469982 Mobile: 91818376
	Document No. 0	
	Document Date 14/10/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZGE20R	HPXNP S6	09/09/2016	SGR3828G	0	33852	79/DS/SGR3828G

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDGG20W70J005149	2ZR1832142	60	Ong Wen Hong	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS:ECICS TP VEH:SMF3550Z DATE OF ACC:12/10/2024 NUMBER OF REPAIR DAYS: SURVEY BY:				50 100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				120.00
3	B	BP-LAB2 TO REPLACE AND REPAIR ACCIDENT DAMAGED P ARTS				576 x 3 = 1728 2880.00
4	B	BP-RES2 TO RESPRAY ALL ACCIDENT AFFECTED AREAS				472 x 3 = 1416 1888.00
5	B	BP-LAB2 TO CHECK WIRING SYSTEM				97.92
6	B	BP-LAB2 TO DRILL HOLE AND INSTALL REVERSE SENSOR				144.00
7	B	BP-LAB2 TO REMOVE AND TRANSFER BOOT COMPONENT TO NEW BOOT				288.00
8	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				144.00
9	B	BP-WS2 TO REMOVE AND INSTALL REAR WINDSCREEN				369.60
10	S	BP-SUBLET TO SUPPLY SOLAR FILM FOR REAR WINDSCREEN				480.00
11	1	T52159-68907 PLATE,RR BUMPER	1.00	911.60	30.00	638.12
12	2	T52462-68010 PAD, RR BUMPER, RH	2.00	7.50	30.00	10.50
13	3	T52462-68020 PAD, RR BUMPER, RH	2.00	7.50	30.00	10.50
14	4	S52161-0K040 PIECE, RR BUMPER	8.00	5.80	30.00	32.48

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987	S1000026 / ICECICS	Mr Bek Yong Huat 60 Bayshore Road #25-01 Singapore 469982 Mobile: 91818376
	Document No. 0	
	Document Date 14/10/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZGE20R	HPXNP S6	09/09/2016	SGR3828G	0	33852	79/DS/SGR3828G

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDGG20W70J005149	2ZR1832142	60	Ong Wen Hong	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
15	5	T52575-68020 RETAINER, RR BUMPER	1.00	70.20	30.00	49.14
16	6	T52155-68030 SUPPORT, RR BUMPER	1.00	149.10	30.00	104.37
17	7	T52576-68020 RETAINER, RR BUMPER	1.00	70.20	30.00	49.14
18	8	T52156-68030 SUPPORT, RR BUMPER	1.00	149.10	30.00	104.37
19	9	T58307-68031 PANEL SUB-ASSY, BODY	1.00	817.70	30.00	572.39
20	0	T67935-68020 B0 PLATE, BACK DOOR	1.00	413.40	30.00	289.38
21	1	T67005-68041 PANEL SUB-ASSY, BACK	1.00	2263.80	30.00	1584.66
22	2	T67881-68030 WEATHERSTRIP, BACK	1.00	465.30	30.00	325.71
23	3	T68105-68071 GLASS SUB-ASSY, BACK	1.00	1480.50	30.00	1036.35
24	4	T69350-28151 LOCK ASSY, BACK DOOR	1.00	571.50	30.00	400.05
25	5	T90975-02086 EMBLEM, SYMBOL	1.00	73.50	30.00	51.45
26	6	T75444-68010 PLATE, LUGGAGE COMPT	1.00	56.90	30.00	39.83
27	7	T89997-30070 ANTENNA, ELECTRICAL	1.00	266.20	30.00	186.34
28	8	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	2.00	108.00	30.00	151.20
29	9	T21000-22 SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00	30.00	140.00

Steve (LKK)
13/5/25, 10.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total 12,287.50
	Please acknowledge receipt of vehicle	Parts 5,775.98	GST 9.00% 1,105.88
		Labour 6,031.52	
		Sublet 480.00	
		Lubrication/Fluid 0.00	Less 0.00
		Others 0.00	Amount Due 13,393.38

6-5 days

Customer Copy