



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24100233/Unh3e2
75 BRAS BASAH ROAD	Date:	21/10/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJZ 4648A	Veh. Inspected	FBE 5763Z
Policy No.	-	Coverage	0
Claim No.	MT/1299325-001	Excess	\$0.00
Assign From	EILEEN LEE	Assign Date	11/10/2024

2. Vehicle Details

Make & Model	YAMAHA T135	C.C	135
Engine No.	5YP302480	Year of Reg.	15/06/2010
Chassis No.	5YP302480	Colour	SILVER
Odometer	40218 KM	Steering	DAMAGED
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	70-90-17	MAXXIS	5
L/H Front Tyre			
R/H Rear Tyre	80-90-17	MAXXIS	5
L/H Rear Tyre			

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/10/2024	Inspection Date	14/10/2024 (10:38)
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days