

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No.

auto	56 3561 FAX: 6256 4 199607198R GST Re 19-9607198-R	
Affiliated to Federation Interna	ationale Des Expe	rts En Automobile
MS LONPAC INSURANCE BHD	Ref:	CS3/LPC24100234/Anh3m4
300 BEACH ROAD	Date:	08/11/2024

			Code:	LPG2	
1.	1. Policy Particulars :- PRE-REPAIR SURVEY				
	Insured Veh.	XD 5375E	Veh. Inspected	SJD 3383K	
	Policy No.	-	Coverage	0	
	Claim No.	23/24/24/VC05/030011	Excess	\$0.00	
	Assign From	ERIC WOO	Assign Date	11/10/2024	
2.	2. Vehicle Details				
	Make & Model	MERCEDES BENZ B200	C.C	2035	
	Engine No.	26696030346678	Year of Reg.	26/12/2007	
	Chassis No.	WDD2452332J220971	Colour	MAROON	
	Odometer	146026 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			

3.		Conditions of Tyres			
		Size	Make	Balance (mm)	
	R/H Front Tyre	215/45R17	WEST LAKE	6	
	L/H Front Tyre	215/45R17	WEST LAKE	6	
	R/H Rear Tyre	215/45R17	WEST LAKE	6	
	L/H Rear Tyre	215/45R17	WEST LAKE	6	

4. Description of Damages

#17-04/07 THE CONCOURSE SINGAPORE 199555

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND REAR WINDSCREEN SHATTERED.

DAMAGES SEE DETAILS.

5.	5. General Information			
	Accident Date	10/10/2024	Inspection Date	14/10/2024
	Survey held at	SIN SENG HONG SPRAY PAINTING & SERVICES 3023A UBI ROAD 1 #01-63 SINGAPORE 408717		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days