



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No. 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

Steve CLKK)
15/10/24, 12:40pm

W R
PIP
by RCLY
5 days

ESTIMATE

Account Details			Account No.		Customer Details		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICC11		Mdm Kiew Li Li 484 Choa Chu Kang Avenue 5 #07-02 Singapore 680484 Mobile: 97853910		
			Document No. 0				
			Document Date 11/10/2024				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	ZRE210R	GEXGPZ S1	23/06/2021	SNA4350S	0	33820	72/DS/SNA4350S
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MR2BE3BE700015074		1ZR0H04349	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY-AI TP INS:CHINA TAIPING INSURANCE TP VEH:SKZ7750E DATE OF ACC:09.10.2024				59	100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				100	200.00
3	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR				/	198.00
4	B	BP-LAB2 CHECK WIRING SYSTEM				/	134.64
5	B	BP-LAB2 REMOVE AND TRANSFER BOOTLID COMPONENTS ONTO NEW BOOTLID. R/I REAR REVERSE CAMERA TO FAC REPAIR.				/	594.00
6	B	BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR 396				?	792.00
7	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				/	198.00
8	B	BP-MECH2 TO CONDUCT ADJUSTMENT ON BLIND SPOT SENS OR				/	198.00
9	S	BP-SUBLET SUPPLY NO PLATE				X	80.00
10	B	BP-LAB2 REPLACE ACC DAMAGED PARTS 792x2				1584	3168.00
11	B	BP-RES2 RESPRAY ACC AFFECTED AREAS 656x2				1312	2624.00
12	1	SPC507-12005 17 BACK SENSOR (1D4, SILVER METAL (photo) REC (SAK new type)	1.00	224.10		/	224.10
13	2	S52159-0Z961 COVER, RR BUMPER L/C / OP	1.00	824.30			824.30
14	3	S52462-02340 PAD, RR BUMPER, RH / MC	2.00	28.00			56.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts		Less Amount Due
					Labour		
					Sublet		
					Lubrication/Fluid		
				Others			

Customer Copy



Borneo Motors



TOYOTA

hcapo
 S. Reg No. : 196700086Z
 ST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCH1 Document No. 0 Document Date 11/10/2024	Mdm Kiew Li Li 484 Choa Chu Kang Avenue 5 #07-02 Singapore 680484 Mobile: 97853910

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	ZRE210R	GEXGPZ S1	23/06/2021	SNA4350S	0	33820	72/DS/SNA4350S

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MR2BE3BE700015074	1ZR0H04349	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
15	4	S52161-02905 PIECE, RR BUMPER L/C / <i>BR</i>	1.00	22.50		22.50
16	5	S52575-02220 RETAINER, RR BUMPER X	1.00	153.50		153.50
17	6	S52562-02330 RETAINER, RR BUMPER, X	1.00	153.50		153.50
18	7	S52576-02220 RETAINER, RR BUMPER X	1.00	153.50		153.50
19	8	S52563-02300 RETAINER, RR BUMPER, X	1.00	153.50		153.50
20	9	S52023-02240 REINFORCEMENT SUB-AS	1.00	512.40		512.40
21	0	S81910-02280 REFLECTOR ASSY, REFL X	1.00	54.10		54.10
22	1	S81920-02360 REFLECTOR ASSY, REFL X	1.00	54.10		54.10
23	2	T90975-02062 EMBLEM, SYMBOL / <i>MC</i>	1.00	66.30		66.30
24	3	S75442-02520 PLATE, LUGGAGE COMPT / <i>MC</i>	1.00	56.70		56.70
25	4	S75442-02530 PLATE, LUGGAGE COMPT / <i>MC</i>	1.00	63.20		63.20
26	5	S64401-02F60 PANEL SUB-ASSY, LUGG	1.00	1314.90		1314.90
27	6	S64600-02080 LOCK ASSY, LUGGAGE C	1.00	553.10		553.10
28	7	T89997-30100 ANTENNA, ELECTRICAL	1.00	100.00		100.00
29	8	S81497-02070 COVER, RR COMBINATIO X	1.00	48.20		48.20
30	9	S81498-02070 COVER, RR COMBINATIO X	1.00	48.20		48.20
31	0	S52161-0K040 PIECE, RR BUMPER / <i>MC</i>	10.00	5.80		58.00

For & on behalf of Borneo	Customer's Signature	Charge Summary	Total 12,956.74
	Signature of vehicle	Parts 4,670.10 Labour 8,206.64 Sublet 80.00 Lubrication/Fluid 0.00 Others 0.00	GST 9.00% 1,166.11 Less 0.00 Amount Due 14,122.85

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Customer Copy

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	10/10/2024 14:46 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	09/10/2024 18:20 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	Exit from Marina Bay Sands Convention and Hall carpark towards Bayfront Road
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SNA4350S
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	KIEW LI LI
NRIC No	S7576322J
Email Address	HSYEW@SINGNET.COM.SG
Mobile Phone No	(Phone) +65-97853910
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Corolla
Variant	COROLLA ALTIS 1.6
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1598
Vehicle Fuel	-
First Registration Date	-
Chassis no	-
Effective Date/Time of Ownership	-

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	7210060328-02

DRIVER

Name of Driver	YEW HOE SOON
NRIC No	S7679387E
Date Of Birth	31/08/1976
Occupation	Indoor
Driving Pass Date	11/05/2009
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience	15 YEARS AND 5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97853910
Alt. Phone Number	-
Email Address	HSYEW@SINGNET.COM.SG
Address	484 CHOA CHU KANG AVENUE 5
Address complement	#07-02 SINGAPORE
Postcode	680484
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Friend
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Others/INDOOR
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

On 08 Oct 2024, 18:20(6.20pm), my car driven by my husband Toyota Altis SNA4350S was on the way to exit from Marina Bay Sands Convention and Hall carpark towards Bayfront road. There were a lot of cars at that time exiting out from the carpark, so he was waiting/queueing on the straight road that will lead up to exit the carpark and due to the traffic, cars in front were not moving. And right behind my car is Honda Vezel SKZ 7750E driven by Nicholas Neo Aik Ban, S7309752E had just moved and crashed to the back of my car. The collision/crashed had cause my car boot, rear bumper and the rear bumper tow hook cover cap to be damaged. Other such as reversing sensor and others need to be checked by toyota technician. Detailed of the accident refer to my car camera record and also photos.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKZ7750E
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	(Phone) +65-96907887
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

