



Borneo Motors

hatchape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388



ESTIMATE

Account Details	Account No.	Customer Details
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987	S1000026 / ICECICS	Mr Meng Fanwei 927 Yishun Central 1 #05-159 Singapore 760927 Mobile: 85001556
	Document No. 0	
	Document Date 22/06/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AGL25R	AWTGZ L3	27/04/2018	SNP5916A	0	24569	77/OD/SNP5916A
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTJBAMCA302050619	8ARW806747	60	Cheng Wei Ting	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:MPC24A0C121800 ACC DATE:21/06/2024 TOW/DRIVE IN:21/06/2024 EXCESS:750.00\$ DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50 100.00
2	B	BP-LAB3 TO CHECK WIRING AND CONDUCT WATER LEAK T EST				192.00
3	B	BP-LAB3 TO DRILLS HOLES AND INSTALL FRONT BUMPER SENSOR				192.00
4	B	BP-ECU3 TO RESET ECU & REPROGRAMME				192 240.00
5	B	BP-MECH3 TO CONDUCT ADJUSTMENT ON FRONT WAVE RADA R SENSOR				192.00
6	B	BP-MECH3 TO CONDUCT ADJUSTMENT ON WHEEL ALIGNMENT				192.00
7	B	BP-MECH3 TO CONDUCT ADJUSTMENT ON WHEEL BALANCING AND REPLATYRE RIM				192.00
8	B	BP-MECH3 TO REPLACE AND REPAIR ON FRONT ENGINE'S MECHANISMAND COMPONENT - WIPER NOZZLE, RADIATOR, A IRCONCONDENSOR, HEADLAMP ECU AND ETC				X 1152.00
9	Z	BP-SLANT SUPPLY SEALANT (NETT)				100 200.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388



ESTIMATE

Account Details		Account No.	Customer Details	
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987		S1000026 / ICECICS	Mr Meng Fanwei	
		Document No. 0	927 Yishun Central 1 #05-159 Singapore 760927	
		Document Date 22/06/2024	Mobile: 85001556	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AGL25R	AWTGZ L3	27/04/2018	SNP5916A	0	24569	77/OD/SNP5916A
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTJBAMCA302050619		8ARW806747	60	Cheng Wei Ting	--/--/----		0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	B	BP-LAB3 TO REPLACE AND REPAIR ON ACCIDENT AFFECTED AREA				
11	B	BP-RES3 TO SPRAY PAINTING ON ACCIDENT AFFECTED AREA				
12	1	L52119-4D938 COVER, FR BUMPER <i>torn</i>	1.00	1746.60	30.00	1222.62
13	2	L89348-48010 RETAINER, ULTRASONIC <i>re</i>	2.00	26.90	30.00	37.66
14	3	L52127-48140 COVER, FR BUMPER <i>X</i>	1.00	66.90	30.00	46.83
15	4	L52128-48110 COVER, FR BUMPER <i>X</i>	1.00	66.90	30.00	46.83
16	5	L53142-48040 GARNISH, RADIATOR <i>scr</i>	1.00	105.20	30.00	73.64
17	6	L81482-48200 COVER, FOG LAMP, LH <i>scr</i>	1.00	172.60	30.00	120.82
18	7	L53286-48020 COVER, FR BUMPER ARM <i>?</i>	1.00	111.90	30.00	78.33
19	8	L52126-48091 BRACKET, FOG LAMP <i>?</i>	1.00	223.70	30.00	156.59
20	9	L53384-22070 CUSHION, HOOD, CTR <i>X</i>	2.00	11.50	30.00	16.10
21	0	L52535-48050 RETAINER, FR BUMPER <i>X</i>	1.00	191.70	30.00	134.19
22	1	L52536-48040 RETAINER, FR BUMPER <i>?</i>	1.00	191.70	30.00	134.19
23	2	L52438-48020 COVER, FR BUMPER <i>scr</i>	1.00	187.40	30.00	131.18
24	3	L75392-35220 RETAINER, OUTSIDE <i>re</i>	2.00	5.60	30.00	7.84
25	4	L52411-48030 GUARD, FR BUMPER <i>X</i>	1.00	223.70	30.00	156.59
26	5	L52618-48021 ABSORBER, FR BUMPER, <i>?</i>	1.00	256.60	30.00	179.62
27	6	T90467-07215 CLIP <i>?</i>	2.00	3.60	30.00	5.04

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

hatchbacks

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388



ESTIMATE

Account Details		Account No.	Customer Details						
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987		S1000026 / ICECICS	Mr Meng Fanwei 927 Yishun Central 1 #05-159 Singapore 760927 Mobile: 85001556						
		Document No. 0							
		Document Date 22/06/2024							
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2018	AGL25R	AWTGZ L3	27/04/2018	SNP5916A	0	24569	77/OD/SNP5916A		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTJBAMCA302050619		8ARW806747	60	Cheng Wei Ting	--/--/----		0.00 --/--/----		
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
28	7	L52611-48181	ABSORBER, FR BUMPER ?			1.00	155.70	30.00	108.99
29	8	L52021-48051	REINFORCEMENT ?			1.00	1142.30	30.00	799.61
30	9	L53395-48080	SEAL, HOOD TO h			1.00	71.10	30.00	49.77
31	0	L53111-48330	GRILLE, RADIATOR X			1.00	1862.00	30.00	1303.40
32	1	L53112-48320	GRILLE, RADIATOR, X			1.00	458.40	30.00	320.88
33	2	L53121-48130	MOULDING, RADIATOR X			1.00	824.70	30.00	577.29
34	3	L53122-48050	MOULDING, RADIATOR X			1.00	1347.40	30.00	943.18
35	4	L53301-48180	HOOD SUB-ASSY st			1.00	4260.70	30.00	2982.49
36	5	T90950-06096	TAPE, SEAL rec			2.00	6.20	30.00	8.68
37	6	L53381-48100	SEAL, HOOD TO X			1.00	102.30	30.00	71.61
38	7	L53802-48140	FENDER SUB-ASSY, FR st			1.00	2304.00	30.00	1612.80
39	8	L53808-48060	REINFORCEMENT ?			1.00	237.10	30.00	165.97
40	9	L53384-22070	CUSHION, HOOD, CTR X			2.00	11.50	30.00	16.10
41	0	L53883-48050	SEAL, FR FENDER, LH rec			1.00	149.20	30.00	104.44
42	1	T53857-47011	RETAINER, FR WHEEL rec			3.00	3.10	30.00	6.51
43	2	L53154-48030	GUIDE, FR SIDE AIR, rec			1.00	123.30	30.00	86.31
44	3	L53748-48020	PLATE, AIR SEALED, de			1.00	84.30	30.00	59.01
45	4	L53806-48190	SHIELD SUB-ASSY, de			1.00	767.60	30.00	537.32
46	5	L75602-48050	MOULDING SUB-ASSY, de			1.00	313.50	30.00	219.45
47	6	L81185-48D30	UNIT, HEADLAMP bro			1.00	13364.40	30.00	9355.08
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total			
		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due			

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388



ESTIMATE

Account Details	Account No.	Customer Details
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987	S1000026 / ICECICS	Mr Meng Fanwei 927 Yishun Central 1 #05-159 Singapore 760927 Mobile: 85001556
	Document No. 0	
	Document Date 22/06/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AGL25R	AWTGZ L3	27/04/2018	SNP5916A	0	24569	77/OD/SNP5916A
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTJBAMCA302050619	8ARW806747	60	Cheng Wei Ting	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
48	7	L81056-48C80 COMPUTER SUB-ASSY?	1.00	1879.80	30.00	1315.86
49	8	L81220-48051 LAMP ASSY, FOG, LH?	1.00	516.00	30.00	361.20
50	9	L89341-48040 C3 SENSOR, ULTRASONIC, X	2.00	503.90	30.00	705.46
51	0	L89341-48040 J0 SENSOR, ULTRASONIC, ?	2.00	630.40	30.00	882.56
52	1	L85354-48030 J0 COVER, HEADLAMP X	1.00	32.20	30.00	22.54
53	2	L85361-48010 BRACKET, WASHER, m	1.00	47.10	30.00	32.97
54	3	L85362-48010 BRACKET, WASHER, m	1.00	47.10	30.00	32.97
55	4	L85208-48110 ACTUATOR SUB-ASSY, ?	1.00	953.20	30.00	667.24
56	5	T90075-17011 JOINT ?	2.00	27.20	30.00	38.08
57	6	T90075-15088 HOSE ?	1.00	31.50	30.00	22.05
58	7	L42611-48851 WHEEL, DISC son	1.00	4776.80	30.00	3343.76
59	8	L67002-48160 PANEL SUB-ASSY, FR repair	1.00	3614.30	30.00	2530.01

Passul
hp 90010068
7 days
24/06/24
EXCESS: 500
Reuter
Reg 64 paint

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	42,240.46
	Please acknowledge receipt of vehicle	Parts 31,831.66 Labour 10,408.80 Sublet 0.00 Lubrication/Fluid 0.00 Others 0.00	GST 9.00%	3,801.64
			Less	0.00
			Amount Due	46,042.10

Customer Copy