

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road #16-00
 Springleaf Tower
 Singapore 079909
 Tel : 6389 - 6111
 Fax : 6224 - 7478 / 7175

Hui Rong

Quotation
 DATE : 27.11.2024
 VEH NO : GBD912Z
 MODEL : Toyota Dyna
 D O A : 11.10.2024
 YR REF : XE976Z

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR GBD912Z (TOYOTA DYNA)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Panel <i>Dented</i>	1	1,281.90 ✓
2	Front Panel Dyna Wording <i>new</i>	1	89.90 ✓
3	Front Grille <i>new</i>	1	622.90 ✓
4	Front Grille Logo <i>new</i>	1	71.20 ✓
5	Head Lamp - LH <i>new</i>	1	1,105.90 ✓
6	Front Corner Panel - LH <i>Repis</i>	1	388.50 ✓
7	Front Panel Top Moulding - Centre <i>could</i>	1	412.40 ✓
8	Front Panel Top Moulding - LH <i>could</i>	1	144.20 ✓
9	Wiper Panel Garnish <i>Dented</i>	1	476.20 ✓
10	Front Wing Mirror - Rectangular <i>new</i>	1	185.30 ✓
11	Front Wing Mirror - Round <i>new</i>	1	98.90 ✓
12	Front Wing Mirror Stay Cover <i>could</i>	1	176.50 ✓
13	Front Windscreen Glass <i>could</i>	1	1,322.40 ✓
14	Front Windscreen Glass Moulding <i>new</i>	1	327.60 ✓
15	Tailgate Lock Cover <i>new</i>	1	55.90 ✓
16	Front Bumper <i>new</i>	1	621.60 ✓
17	Front Bumper Bracket <i>new</i>	1	219.10 ✓
18	Air Con Blower <i>new</i>	1	1,845.90 ✓
19	Air Con Cooling Coil <i>new</i>	1	1,338.70 ✓
	<i>Front Wing Mirror Stay 295 ✓</i>		
	<i>Best</i>		
			\$ 10,785.00
	Less 25%		\$ (2,696.25)
			\$ 8,088.75

S/NETT ITEMS

1	Front Panel Sealant <i>new</i>	1 set	60.00 ✓
2	Front Grille Clips <i>new</i>	1 set	30.00 ✓
3	Front Panel Top Moulding Centre Clips <i>new</i>	1 set	30.00 ✓

RE : ESTIMATE FOR ACCIDENT REPAIR GBD912Z (TOYOTA DYNA)

4	Front Panel Top Moulding LH Clips <i>neu</i>	1 set	20.00 ✓
5	Wiper Panel Garnish Clips <i>neu</i>	1 set	30.00 ✓
6	Front Wing Mirror Stay Cover Clips <i>neu</i>	1 set	20.00 ✓
7	Front Windcreens Sealant <i>neu</i>	1 set	60.00 ✓
8	ERP Bracket <i>neu</i>	1	30.00 ✓

280.00

Total parts

\$ 8,368.75

LABOUR CHARGE

1	To knocking out front portion & renew above parts	\$ 1,200.00 <i>500</i>
2	To putty & spray up paint works	\$ 1,200.00 <i>600</i>
3	To check wiring	\$ 50.00 <i>30</i>
4	To apply tuff coat	\$ 150.00 <i>60</i>
5	To remove front windscreen glass	\$ 180.00 <i>120</i>
6	To remove dashboard	\$ 350.00 <i>+</i>
7	To remove aircon system	\$ 380.00 <i>+</i>

Total Labour

\$ 3,510.00

Grand Total

\$ 11,878.75

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling.
1/s 05/05/15
05 Days
total: 4954.57
1/s : 3950