

ASS. REC. BY:

REF:

0721

CS/CT124100240/Knp3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Vsh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/10 11:00 AM @ 41501. Calm (Red. \$13490.07, 76%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 14/10/2024
VEHICLE : SNJ3651H
MAKE/MODEL : TOYOTA PRIUS
CHASSIS NO : ZVW51-6144847
MILLAGE :
TYRE SIZE : 195/65/R15
DOA : 10/10/2024
TP INSURANCE : CHINA TAIPING

Not Authorized
LI Peng @ 4150kr
Repair After Paint
5 days

List items

01 PC	REAR TAIL GATE	1641.50	By \$	2,699.41	✓
01 PC	REAR TAIL GATE INNER LOCK		nd \$	395.43	✓
01 PC	REAR TAIL GATE INNER LOCK COVER		\$	19.14	X
01 PC	REAR TAIL GATE CATCH LOCK		\$	48.42	X
01 PC	REAR TAIL GATE WEATHERSTRIP		\$	355.07	X
01 PC	REAR TAIL GATE INNER TRIM BOARD		my \$	332.04	✓
01 PC	REAR TAIL GATE INNER HANDLE		\$	76.10	X
01 PC	REAR TAIL GATE LH GANISH		\$	65.76	X
01 PC	REAR TAIL GATE OUTER HANDLE		\$	286.30	X
01 PC	REAR TAIL GATE OUTER MOULDING		\$	1,303.29	X
01 PC	REAR TAIL GATE EMBLEM (PRIUS)		un \$	101.44	X
01 PC	REAR TAIL GATE EMBLEM (HYBRID)		un \$	106.08	X
01 PC	REAR TAIL GATE EMBLEM (LOGO)		\$	104.60	X
01 PC	REAR LH TAIL GATE LAMP		\$	524.84	X
01 PC	REAR LH LOWER TAIL LAMP		my \$	494.48	✓
01 PC	REAR LH UPPER TAIL LAMP		\$	733.20	X
01 PC	REAR LH TAIL LAMP BRACKET		\$	85.63	X
01 PC	REAR BUMPER	127 488.50	By \$	2,792.23	✓
01 PC	REAR BUMPER DISFUFER		nd \$	460.95	✓
01 PC	REAR BUMPER SIDE RETAINER LH		\$	144.86	✓
01 PC	REAR LH BUMPER SIDE SHEILD		\$	89.56	X
01 PC	REAR REINFORCEMENT		\$	563.20	X
01 PC	REAR LH REFELCTOR		cm \$	64.32	✓
01 PC	REAR END PANEL		\$	654.84	✓
01 PC	REAR END PANEL TOP GANISH		nd \$	215.36	✓
01 PC	REAR LH TOP KEY ANTENNA SENSOR		\$	71.48	✓
01 PC	REAR LH LOWER KEY ANTENNA SENSOR		\$	65.04	X
01 PC	REAR END PANEL KEY ANTENNA SENSOR		\$	83.00	X
TOTAL PARTS COST			\$ 12,936.07		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

258

Special Nett Item:

06 PC	REAR BUMPER CLIP @ \$6.00
10 PC	REAR TAIL GATE INNER TRIM BOARD CLIP @ \$6.00
08 PC	REAR TAIL GATE OUTER GANISH CLIP @ \$6.00
02 PC	REAR PARKING SENSOR @ \$280
01 PC	WINDSCEEN SEALANT

nn	\$	36.00	✓
nn	\$	60.00	X
nn	\$	48.00	X
	\$	560.00	X
nn	\$	100.00	40/12
	\$	804.00	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA
3. TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL
4. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS
5. TO SUPPLY LABOUR TO DISMANTLE AND REFIX WINDSCREEN & GLASS
6. TO SUPPLY LABOUR TO DIANOGTIS

	\$	1,500.00	600/
	\$	1,000.00	600/
	\$	400.00	30/
	\$	200.00	20/
	\$	500.00	180/
nn	\$	300.00	X
	\$	3,900.00	

TOTAL PARTS

\$ 12,936.07

SPECIAL NETT ITEM

\$ 804.00

TOTAL LABOUR

\$ 3,900.00

TOTAL COST OF REPAIR

\$ 17,640.07