

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliate data Forderection Internationals Box Formerts For Australia III					
Affiliated to Federation Internationale			·		
MS	INCOME INSURANCE LTD		Ref:	CS/INC24100241/Dvh3e2	
	75 BRAS BASAH ROAD INCOME CENTRE SINGAPORE 189557		Date:	07/11/2024	
			Code:	INC	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBG 2713C	Veh. Inspected	SMY 600H	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1298648-002	Excess	\$0.00	
	Assign From	MARCUS XIAO	Assign Date	14/10/2024	
2.	2. Vehicle Details				
	Make & Model	B.M.W. M3	C.C	2979	
	Engine No.	07229068S55B30A	Year of Reg.	29/06/2015	
	Chassis No.	WBS3C92010P818164	Colour	GREEN	
	Odometer	103455 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.	3. Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	255/35R19	BRIDGESTONE	5	
	L/H Front Tyre	255/35R19	BRIDGESTONE	5	
	R/H Rear Tyre	255/35R19	BRIDGESTONE	5	
	L/H Rear Tyre	255/35R19	BRIDGESTONE	5	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	02/10/2024	Inspection Date	16/10/2024 (11:27)	
	Survey held at	25 KAKI BUKIT ROAD 4, SYNERGY @ KB, #07-38 SINGAPORE 417800 - REPAIRER: 11 VINYLS			
5a.	5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate Day	s of Repair		

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days