



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE P1

1 GATEWAY DRIVE #15-08
WESTGATE TOWER
SINGAPORE 608531

TEL :

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : GBA2165R

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE

ACCIDENT DATE : 02/10/2024

TP VEH REG NO : GBA2165R

ESTIMATE

NO : QUOT202410-000024(00)

DATE : 14/10/2024

POLICY NO : SP2003907937

VEH REG NO : SNT1390X

MAKE/MODEL : MERCEDES BENZ GLC200
AMG LINE (R19 LED)

CHASSIS NO : W1N2539802F974405

ENGINE NO : 26492030420990

REG. DATE : 2021

Not Notched

Resurvey B4 pain

4 days

88043-60

Estimate Repair Cost to Vehicle No : SNT1390X

Description	Quantity	Unit Price	Amount
		SS	SS
NET PRICE			
1 Headlamp assy	1	3,780.00	3,780.00
2 Front fender	1	1,110.00	1,110.00
3 Front fender inner shield - LH (front)	1	310.00	310.00
4 Front fender inner shield - LH (rear)	1	226.00	226.00
5 Front fender wheel arch garnish - LH	1	250.00	250.00
6 Front bumper	1	2,000.00	2,000.00
7 Front bumper side retainer	1	24.00	24.00
8 Front bumper fog lamp cover - LH	1	123.00	123.00
			7,823.00
		Less 10%	782.30
			7,040.70
SPECIAL NET			
9 Front tyre - LH	1	480.00	480.00
			480.00
LABOUR			
10 To remove & refit front bumper sensor	1	100.00	100.00
11 To check & rectify wiring system	1	80.00	80.00
12 To panel beat & straighten LH front fender inner panel, LH front chassis frame, including replacement of parts and align where necessary, to refit & adjust the same	1	1,000.00	1,000.00
13 To putty and spray paint on affected areas	1	1,000.00	1,000.00
14 To apply rust-proofing on repaired and replaced panels	1	80.00	80.00
15 To reset & reprogram headlamp fault code	1	350.00	350.00
16 To computerise check wheel alignment	1	120.00	120.00
			2,730.00
		TOTAL	SS 10,250.70
		ADD GST @ 9.00%	922.56
		GRAND TOTAL	SS 11,173.26

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE DOLLAR ELEVEN THOUSAND ONE HUNDRED SEVENTY-THREE AND CENTS TWENTY-SIX ONLY