

ASSIGNMENT

From: _____ Date: _____

Estn: _____

OD / TP RES / CD RES / EVA / INV / MVTo in Vehicle No: _____at W/O _____

of _____

Insured: **SGL 165L**

Policy No: _____

Claims No: **C10032228/MC**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vcl: _____

(Policy Condition)

N/S	O/S

Remarks: There had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SDT8080M** Yr Regn: **2017, Nov**Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Infinity Q50** C.C. **1991**Colour: **Grey** A/C: Insured / Std / NI / NASp. Reading: **155464** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **JN18CAV3720530107**Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModif: Nil / S/Rim / STD A/Rim orTyre Size: F: **225/50R18**
R: **225/50R18**BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. **06** mm R/Bal. **06** mmL/Bal. **06** mm L/Bal. **06** mmD.O.A. **13/10/24**D.O.I. **14/10/24**Survey held at **N51**Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19/11/24 **TP Budget Street**
Adrian confirmed LS \$5100 (Red 5847.10, 53%)

COE Expiry: _____

Estimate given during: Yes (✓)
1st Survey: No ()

MV:

PV:

Nett:

9396

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: **3**

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$

Survey Fee:

Transportation:

3 + R.S. \$1

Photos

Others

Report Format:

Report Format:

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GOH CHEE TIONG
BLK 2B HONG SAN WALK #05-11
SINGAPORE 689048

Contact : 94787231 96609661

TAX INVOICE

Repair Code : CLM18410

Date in : 14/10/2024

Vehicle Num. : SDT8080M

Model : INFINITI Q50 2.0T A/T (R18) EU6 NAV

Chassis/Eng# : JN1BCAV37Z0530107/274AE078100A

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Assembled</i>	1	890.80	✓ 890.80
FRONT BUMPER FOGLAMP OUTER GARNISH WITH CHROME <i>Assembled</i>	1	158.40	✓ 158.40
FRONT BUMPER LH DAYLAMP <i>Assembled</i>	1	496.60	✓ 496.60
FRONT BUMPER LH FOGLAMP <i>Assembled</i>	1	361.90	✓ 361.90
FRONT BUMPER LH PARKING SENSOR <i>1 piece day d</i>	2	258.20	<i>258.20</i> 516.40
FRONT BUMPER LH PARKING SENSOR 'O' RING <i>1 piece M</i>	2	15.00	<i>15</i> 30.00
FRONT BUMPER LH REINFORCEMENT BRACKET <i>pc n</i>	1	215.90	+ 215.90
FRONT BUMPER LH SIDE RETAINER <i>pc n</i>	1	47.30	+ 47.30
FRONT BUMPER LOWER GRILLE <i>pc n</i>	1	407.80	+ 407.80
FRONT BUMPER PARKING SENSOR HOLDER <i>pc n</i>	4	53.20	✓ 212.80
FRONT BUMPER REINFORCEMENT <i>pc n</i>	1	900.40	+ 900.40
FRONT BUMPER SPONGE <i>Assembled</i>	1	315.20	✓ 315.20
FRONT BUMPER TOP SIDE BRACKET <i>pc n</i>	1	108.60	+ 108.60
FRONT BUMPER TOW HOOK COVER <i>pc n</i>	1	29.30	+ 29.30
FRONT GRILLE <i>Assembled</i>	1	606.80	✓ 606.80
FRONT GRILLE 'LOGO' EMBLEM <i>pc n</i>	1	88.80	✓ 88.80
FRONT LH HEADLAMP <i>Assembled</i>	1	3628.00	✓ 3,628.00
FRONT SUPPORT PANEL <i>pc n</i>	1	954.00	+ 954.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GOH CHEE TIONG
BLK 2B HONG SAN WALK #05-11
SINGAPORE 689048

Contact : 94787231 96609661

TAX INVOICE

Repair Code : CLM18410

Date in : 14/10/2024

Vehicle Num. : SDT8080M

Model : INFINITI Q50 2.0T A/T (R18) EU6 NAV

Chassis/Eng# : JN1BCAV37Z0530107/274AE078100A

Subtotal before discount 9,969.00

Percentage discount 10%

996.90

Sub-total 1

8,972.10

FRONT BONNET INSULATOR CLIPS - SET	1	50.00	+	50.00
FRONT BUMPER CLIPS - SET	1	50.00	30	50.00
FRONT BUMPER NUMBER PLATE	1	25.00	+	25.00
FRONT BUMPER NUMBER PLATE HOLDER	1	50.00	+	50.00
FRONT GRILLE CLIPS - SET	1	40.00	20	40.00

Subtotal before discount 215.00

Percentage discount 0%

0.00

Sub-total 2

215.00

Parts-total

9,187.10

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

✓ 80.00
200 800.00
300 800.00
+ 80.00

Labour Total

1,760.00

Parts & Labour Total

10,947.10

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To *** damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*** This is a computer-generated document which requires no signature.***

page 2

Adm C
2/5 14/10/24
03 Days