

ASSIGNMENT

Front: _____ Date: _____
 Estn: _____
 OD / TP RES / CD RES / EVA / INV / MV
 To in Vehicle No: _____
 at W/O _____
 of _____
 Insured: _____
 Policy No: _____
 Claim's No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vch: _____
 (Policy Condition)

N/S	O/S

Remark: There had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SDT8080M Yr Regn: 2017, Nov
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Infinity Q50 C.C. 1991

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 158464 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1BCAV3720530107

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modif: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R18

R: 225/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front	Rear
R/Bal. <u>06</u> mm	R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm	L/Bal. <u>06</u> mm
D.O.A. _____	D.O.I. <u>14/10/24</u>

Survey held at N51

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Budget Sheet.</u>
	<u>COE Expiry</u>
	<u>Estimate given during : Yes (✓)</u>
	<u>1st Survey : No ()</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>
	<u>9396</u>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

1) Date/Time, File Return to?

2) _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Insp (\$ _____)

Survey Fee: _____

Transportation: _____

3 + R.S. \$ _____

Photos _____

Others _____

Report Format: _____

Report Format: _____



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GOH CHEE TIONG
 BLK 2B HONG SAN WALK #05-11
 SINGAPORE 689048

Contact : 94787231 96609661

TAX INVOICE

Repair Code : CLM18410

Date in : 14/10/2024

Vehicle Num. : SDT8080M

Model : INFINITI Q50 2.0T A/T (R18) EU6 NAV

Chassis/Eng# : JN1BCAV37Z0530107/274AE078100A

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Assembled</i>	1	890.80	✓ 890.80
FRONT BUMPER FOGLAMP OUTER GARNISH WITH CHROME <i>Assembled</i>	1	158.40	✓ 158.40
FRONT BUMPER LH DAYLAMP <i>Assembled</i>	1	496.60	✓ 496.60
FRONT BUMPER LH FOGLAMP <i>Assembled</i>	1	361.90	✓ 361.90
FRONT BUMPER LH PARKING SENSOR <i>1 piece day d</i>	2	258.20	<i>258.20</i> 516.40
FRONT BUMPER LH PARKING SENSOR 'O' RING <i>1 piece M</i>	2	15.00	<i>15</i> 30.00
FRONT BUMPER LH REINFORCEMENT BRACKET <i>pc n</i>	1	215.90	+ 215.90
FRONT BUMPER LH SIDE RETAINER <i>pc n</i>	1	47.30	+ 47.30
FRONT BUMPER LOWER GRILLE <i>pc n</i>	1	407.80	+ 407.80
FRONT BUMPER PARKING SENSOR HOLDER <i>pc n</i>	4	53.20	✓ 212.80
FRONT BUMPER REINFORCEMENT <i>pc n</i>	1	900.40	+ 900.40
FRONT BUMPER SPONGE <i>Assembled</i>	1	315.20	✓ 315.20
FRONT BUMPER TOP SIDE BRACKET <i>pc n</i>	1	108.60	+ 108.60
FRONT BUMPER TOW HOOK COVER <i>pc n</i>	1	29.30	+ 29.30
FRONT GRILLE <i>Assembled</i>	1	606.80	✓ 606.80
FRONT GRILLE 'LOGO' EMBLEM <i>pc n</i>	1	88.80	✓ 88.80
FRONT LH HEADLAMP <i>Assembled</i>	1	3628.00	✓ 3,628.00
FRONT SUPPORT PANEL <i>pc n</i>	1	954.00	+ 954.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GOH CHEE TIONG
BLK 2B HONG SAN WALK #05-11
SINGAPORE 689048

Contact : 94787231 96609661

TAX INVOICE

Repair Code : CLM18410

Date in : 14/10/2024

Vehicle Num. : SDT8080M

Model : INFINITI Q50 2.0T A/T (R18) EU6 NAV

Chassis/Eng# : JN1BCAV37Z0530107/274AE078100A

Subtotal before discount 9,969.00

Percentage discount 10%

996.90

Sub-total 1

8,972.10

FRONT BONNET INSULATOR CLIPS - SET *men*

1

50.00

+ 50.00

FRONT BUMPER CLIPS - SET *men*

1

50.00

30 ~~50.00~~

FRONT BUMPER NUMBER PLATE *men*

1

25.00

+ 25.00

FRONT BUMPER NUMBER PLATE HOLDER *men*

1

50.00

↑ 50.00

FRONT GRILLE CLIPS - SET *men*

1

40.00

20 ~~40.00~~

Subtotal before discount

215.00

Percentage discount 0%

0.00

Sub-total 2

215.00

Parts-total

9,187.10

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

✓ 80.00

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

200 800.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

300 800.00

To apply anti-rust chemical on repaired and replaced panel.

+ 80.00

Labour Total

1,760.00

Parts & Labour Total

10,947.10

LKK Auto Consultants hence notify
the Repairer of the following:

• To resurvey before/after spray painting

• To *** damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

page 2

Adm C
2/5 14/10/24
03 Days