



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

TP Budget Direct.
Veron.

GOH CHEE TIONG

BLK 2B HONG SAN WALK #05-11

SINGAPORE 689048

Contact : 94787231 96609661

TAX INVOICE

Repair Code : CLM18410

Date in : 14/10/2024

Vehicle Num. : SDT8080M

Model : INFINITI Q50 2.0T A/T (R18) EU6 NAV

Chassis/Eng# : JN1BCAV37Z0530107/274AE078100A

2017

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Assembled</i>	1	890.80	✓ 890.80
FRONT BUMPER FOGLAMP OUTER GARNISH WITH CHROME <i>Assembled</i>	1	158.40	✓ 158.40
FRONT BUMPER LH DAYLAMP <i>Assembled</i>	1	496.60	✓ 496.60
FRONT BUMPER LH FOGLAMP <i>Assembled</i>	1	361.90	✓ 361.90
FRONT BUMPER LH PARKING SENSOR <i>1 piece day d</i>	2	258.20	516.40 258.20
FRONT BUMPER LH PARKING SENSOR 'O' RING <i>1 piece new</i>	2	15.00	30.00 15
FRONT BUMPER LH REINFORCEMENT BRACKET <i>new</i>	1	215.90	+ 215.90
FRONT BUMPER LH SIDE RETAINER <i>new</i>	1	47.30	+ 47.30
FRONT BUMPER LOWER GRILLE <i>new</i>	1	407.80	+ 407.80
FRONT BUMPER PARKING SENSOR HOLDER <i>new</i>	4	53.20	✓ 212.80
FRONT BUMPER REINFORCEMENT <i>new</i>	1	900.40	+ 900.40
FRONT BUMPER SPONGE <i>Assembled</i>	1	315.20	✓ 315.20
FRONT BUMPER TOP SIDE BRACKET <i>new</i>	1	108.60	+ 108.60
FRONT BUMPER TOW HOOK COVER <i>new</i>	1	29.30	+ 29.30
FRONT GRILLE <i>Assembled</i>	1	606.80	✓ 606.80
FRONT GRILLE 'LOGO' EMBLEM <i>new</i>	1	88.80	✓ 88.80
FRONT LH HEADLAMP <i>new</i>	1	3628.00	3628.00 3105
FRONT SUPPORT PANEL <i>new</i>	1	954.00	+ 954.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GOH CHEE TIONG
 BLK 2B HONG SAN WALK #05-11
 SINGAPORE 689048

Contact : 94787231 96609661

TAX INVOICE

Repair Code : CLM18410

Date in : 14/10/2024

Vehicle Num. : SDT8080M

Model : INFINITI Q50 2.0T A/T (R18) EU6 NAV

Chassis/Eng# : JN1BCAV37Z0530107/274AE078100A

		Subtotal before discount	6509.50	9,969.00
Percentage discount	10%			996.90
		Sub-total 1	5858.55	8,972.10
FRONT BONNET INSULATOR CLIPS - SET	men	1	50.00	+ 50.00
FRONT BUMPER CLIPS - SET	men	1	50.00	30 - 50.00
FRONT BUMPER NUMBER PLATE	men	1	25.00	+ 25.00
FRONT BUMPER NUMBER PLATE HOLDER	men	1	50.00	50.00
FRONT GRILLE CLIPS - SET	men	1	40.00	20 - 40.00
		Subtotal before discount		215.00
Percentage discount	0%			0.00
		Sub-total 2		215.00
		Parts-total		9,187.10

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

580 ✓ 80.00
 200 ✓ 800.00
 300 ✓ 800.00
 + 80.00

Labour Total 1,760.00

Parts & Labour Total 10,947.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To *** (damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

page 2

Abhinav
 2/s 14/10/24
 03 Days

total: 6488.55
 4/s: 5.11C ✓