

**Adjustment of Spare Parts Costs for Repairs SLS 1034D
HYUNDAI ELANTRA**

List Items			
Item	Qty	Vehicle parts description	\$
1	1	Rear bumper / BR	980.00 495 /
2	2	Rear bumper side retainer LH & RH x nn	80.00
3	1 set	Rear bumper fasteners / Nec	48.00 30 /
4	2	Rear bumper side holder LH & RH x nn	60.00
	2 1	rear bumper reflector lamp LH & RH- / BR	200.00 72.50 /
	1	rear bumper reinforcement / DD	500.00 329 /
6	1	bootlid / DD	1580.00 /
7	1	bootlid inner lock / Jammed	355.00 166 /
8	1	bootlid lamp LH & RH- / BR	1200.00 600 /
13	1	bootlid weatherstrip / TN	285.00 178 /
14	1	bootlid innerboard x nn	355.00
15	1 set	bootlid inner trim clips x nn	35.00
16	1 2	1 - Taillamp bootlid lamp LH & RH- / Cut/BR	1380.00 690 /
	1	Rear end panel / DD	650.00 569 /
22	1	Rear end panel top garnish x nn	285.00
23	1 set	Rear end panel top garnish fasteners x nn	38.00

8031.00

Less 20%

1606.20

6424.80

Special Nett Items

1	rear bumper lower diffuser / Cut	400.00 /
2	Rear end panel sealeant / Nec	60.00 30 /
3	Reverse Sensor x nn	200.00
4	Carplate w housing x nn	60.00
5	rear exhaust muffler chrome tips x nn	200.00
		<u>920.00</u>

Adjustment of Labour Costs for Repairs

Spraying of affected areas	1000.00 800
Carry out body cavity preservation	120.00 30
To remove & replaced damaged parts including straightening & repositioning replacement parts & panel	1000.00 900
Check wiring	80.00 30
Remove/refix boot compartment fittings & attachments for	160.00 80
Remove & refix reverse sensor	120 30

Remove & reinstall rear boot upholstery & vaccum nner 80 [x](#)

Total labour 2560.00

Steve (LKK)
22/10/24, 1.30pm
Without Prejudice
L/S
Resurvey After Spray
7 days