

Date: 14-10-2024
Vehicle No: SKE1661D
Model: Tesla Model 3
Chassis: 5YJ3F7EA2LF572909
Reg.Year: 9.9.2020

Not Withheld
Resurvey B4paim
2 days

Third Party Insurer: China Taiping
Third Party Veh No: GBJ1900U
Date of Accident: 12/10/2024
Estimator: Loong
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1		<i>MB</i> \$766.00
2	FRONT BUMPER LICENCE PLATE MOUNTING BRACKET	1		<i>od</i> \$29.90
3	FRONT BUMPER ENERGY ABSORBER	1		<i>P2</i> \$46.73
4	FRONT PARKING SENSOR	2	\$163.55	<i>in</i> \$327.10
5	FRONT PARKING SENSOR MOUNTING BRACKET SET	1		<i>in</i> \$28.02
SUB TOTAL				\$1,197.75
LESS 10%				-\$119.78
PARTS TOTAL				\$1,077.98

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		<i>nn</i> \$55.00
2	FRONT BUMPER LOWER CLIPS	1		<i>nn</i> \$50.00
3	FRONT FENDER LINER CLIPS	1		<i>nn</i> \$55.00
4	FRONT LICENCE PLATE NUMBER WITH FRAME	1		<i>cm</i> \$140.00
S/N TOTAL				\$300.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

\$400.00 *200*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, ETC

\$350.00 *220*

LABOUR CHARGES TO REMOVE & REPLACE FRONT BUMPER REVERSE SENSOR & ETC.

\$100.00 *60*

TO CHECK WIRING & ELECTRICAL SYSTEM.

nn \$100.00 *X*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LABOUR TOTAL \$950.00

TOTAL \$2,327.98

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 Fax: (+65) 6481 1011

