



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SJW 8244X

| REPLACEMENT OF PARTS | | | | |
|----------------------|------------------------------------|------------------|------------------------|-------------------|
| Qty | Description of Parts | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
| 1 | REAR BUMPER | DEFORMED/CRACKED | \$2,500.00 | \$2,332.84 |
| 1 | REINFORCEMENT | DENTED | \$680.00 | \$680.00 |
| 1 | BUMPER MOULDING CENTRE | NECESSARY | \$180.00 | \$180.00 |
| 2 | BUMPER MOULDING SIDE @\$90.00 | NECESSARY | \$180.00 | \$180.00 |
| 2 | BUMPER LOWER BRACKETS @\$180.00 | CRACKED | \$360.00 | \$220.00 |
| 1 | R/L TAILLAMP BRACKET | CRACKED | \$220.00 | \$165.00 |
| 1 | R/R TAILLAMP BRACKET | CRACKED | \$220.00 | \$165.00 |
| | LESS 0.00 / 10.00% DISCOUNT | | \$0.00 | (\$392.28) |
| | | | \$4,340.00 | \$3,530.56 |

| Special Nett | | | | |
|--------------|----------------------------|-----------|------------------------|-------------------|
| Qty | Description of Parts | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
| 1 | SET REAR BUMPER CLIPS (SN) | NECESSARY | \$50.00 | \$40.00 |
| | | | \$50.00 | \$40.00 |

| Labour | | | | |
|--------|---|-----------|------------------------|-------------------|
| | Description of Parts | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
| | TO REMOVE REAR BUMPER OUT TO FACILITATE REPLACEMENT OF DAMAGED PART | | \$400.00 | \$300.00 |
| | TO RESPRAY REAR BUMPER | | \$400.00 | \$300.00 |
| | | | \$800.00 | \$600.00 |

| | | |
|--------------------|-------------------|-------------------|
| GRAND TOTAL | \$5,190.00 | \$4,170.56 |
|--------------------|-------------------|-------------------|

| | |
|---|-------------------|
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED) | \$3,300.00 |
|---|-------------------|

Report Ref No: CS/INC24100249/Unh3e2

TOTAL FOR SPARE PARTS: \$ 4,390.00 \$ 3,570.56
TOTAL FOR LABOUR : \$ 800.00 \$ 600.00
TOTAL REPAIR COST: \$ 5,190.00 \$ 4,170.56

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.