

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 14.10.2024

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : ~~GBK1184K~~ *GBG1184K*
MODEL : NISSAN NV200
DATE OF ACCIDENT : 08.10.2024
TIME OF ACCIDENT : 12:00 HOURS

Veron

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>torn</i>	1	\$ 560.90	\$ 560.90
2	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 49.70	\$ 99.40
3	REAR BUMPER TOW HOOK COVER <i>new</i>	1	\$ 13.30	\$ 13.30
4	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 37.50	\$ 75.00
5	REAR BUMPER SPONGE <i>new</i>	1	\$ 98.80	\$ 98.80
6	TAIL LAMP RH <i>crash'd</i>	2	\$ 275.80	\$ 551.60
7	TAIL LAMP PANEL RH <i>Buckled</i>	1	\$ 288.30	\$ 288.30
8	TAIL LAMP INNER PANEL RH <i>new</i>	1	\$ 268.50	\$ 268.50
9	REAR SIDE PANEL RH <i>Dented</i>	1	\$ 1,791.60	\$ 1,791.60
10	REAR SIDE PANEL (INNER) RH <i>Repair</i>	1	\$ 1,499.80	\$ 1,499.80
11	REAR SIDE PANEL RAILWAY END GARNISH RH	1	\$ 165.20	\$ 165.20
12	REAR SIDE PANEL INNER AIR VENT RH <i>new</i>	1	\$ 62.60	\$ 62.60
13	REAR SIDE PANEL RAILWAY RH <i>Repair Dented</i>	1	\$ 764.90	\$ 764.90
14	REAR DOOR RH <i>Repair</i>	1	\$ 1,545.90	\$ 1,545.90
15	REAR DOOR LOWER LOCK RH <i>new</i>	1	\$ 159.30	\$ 318.60
16	REAR DOOR LOWER LOCK CHATCHER RH <i>new</i>	1	\$ 65.20	\$ 318.60
17	REAR DOOR HINGE RH <i>new</i>	2	\$ 119.60	\$ 239.20

TOTAL PRICE \$ 8,662.20
LESS 10% \$ 866.22
SUB TOTAL PRICE \$ 7,795.98

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
-----	-------------	-----	-------------	--------------

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBK1184K**
 MODEL : **NISSAN NV200**
 DATE OF ACCIDENT : 08.10.2024
 TIME OF ACCIDENT : 12:00 HOURS

1	REAR NUMBER PLATE <i>the m</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIP (SET) <i>oh</i>	1	\$ 6.50	\$ 6.50	✓
3	TAIL LAMP CLIP (SET) <i>the m</i>	1	\$ 50.00	\$ 50.00	+
4	TAIL LAMP PANEL SEALANT <i>the m</i>	2	\$ 80.00	\$ 160.00	30
5	TAIL LAMP INNER PANEL SEALANT <i>the m</i>	2	\$ 80.00	\$ 160.00	+
6	REAR SIDE PANEL (INNER) SEALANT <i>the m</i>	2	\$ 150.00	\$ 300.00	+
7	REAR SIDE PANEL INNER TRIM CLIP (SET) <i>the m</i>	1	\$ 60.00	\$ 60.00	+
8	REAR DOOR SEALANT <i>2</i>	1	\$ 180.00	\$ 180.00	+
9	REAR DOOR GLASS SEALANT <i>the m</i>	1	\$ 80.00	\$ 80.00	+
10	REAR DOOR GLASS INNER SEAL <i>the m</i>	1	\$ 60.00	\$ 60.00	+
11	REAR DOOR INNER BOARD CLIP (SET) <i>the m</i>	1	\$ 80.00	\$ 80.00	+
12	REAR DOOR STICKER '5PAX' <i>the m</i>	1	\$ 50.00	\$ 50.00	15
13	REVERSE SENSOR <i>the m</i>	1	\$ 250.00	\$ 250.00	+

51.50

TOTAL \$ 1,486.50

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	600
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	500
3	TUFF COAT	\$ 250.00	60
4	WIRING AND BULB CHECK	\$ 80.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 150.00	70
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
8	REMOVE & REINSTALL SLIDING DOOR RAILING	\$ 180.00	X
9	TRANSFER REAR DOOR MECHANISM	\$ 120.00	X

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **GBK1184K**
MODEL : **NISSAN NV200**
DATE OF ACCIDENT : 08.10.2024
TIME OF ACCIDENT : 12:00 HOURS

10	REMOVE & REINSTALL REAR DOOR GLASS	\$ 120.00	X
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$180.00	X

TOTAL \$ 4,640.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 9,282.48
TOTAL LABOUR COST : \$ 4,640.00
TOTAL REPAIR COST : \$ 13,922.48

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
2/s 15/10/24.
OS Pays.

Total: 5041.75
C/S. AK ✓

1280