



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO YR 2923H

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SIDEGATE RH	TO REPAIR SEE LABOUR	\$3,500.00	\$0.00
			\$3,500.00	\$0.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE DAMAGED BODY PARTS WITH ALL NECESSARY COMPONENTS/ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY REPAIR, RESHAPE BODY DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIT AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS/ATTACHMENTS. INCLUSIVE OF THE REPAIR OF SIDEGATE RH		\$350.00	\$200.00
	TO SPRAY PAINT REPLACED/REPAIRED BODY PARTS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS		\$400.00	\$300.00
			\$750.00	\$500.00
GRAND TOTAL			\$4,250.00	\$500.00
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)			\$500.00
Report Ref No: CS/AGI24100253/Unp3m4				

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.