



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24100253/Unp3m4
(BUDGET DIRECT INSURANCE)	Date:	13/11/2024
190 CLEMENCEAU AVENUE #03-01		
SINGAPORE SHOPPING CENTRE SINGAPORE 239924	Code:	AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMM 9116T	Veh. Inspected	YR 2923H
Policy No.	-	Coverage	0
Claim No.	C10032238/CH	Excess	\$0.00
Assign From	NG CHEN HOW	Assign Date	15/10/2024

2. Vehicle Details

Make & Model	HINO XZU710R 14FT WID CAB 5T MT	C.C	4009
Engine No.	N04CWN28670	Year of Reg.	31/07/2024
Chassis No.	JHHUCV3F70K057416	Colour	WHITE
Odometer	3392 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/85R15	BRIDGESTONE	8
L/H Front Tyre	195/85R15	BRIDGESTONE	8
R/H Rear Tyre	195/85R15 (D)	BRIDGESTONE	8/8
L/H Rear Tyre	195/85R15 (D)	BRIDGESTONE	8/8

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/09/2024	Inspection Date	16/10/2024
Survey held at	2 KAKI BUKIT AVE 2 #01-03 KAKI BUKIT AUTOHUB S(417921) - REPAIRER: THINK ONE AUTOCARE PTE LTD		

5a. Remarks

A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS.
B) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days