



THINK ONE AUTOCARE PTE LTD

RCB : 201322501G GST : 201322501G
80 JALAN LAM HUAT, #02-32 CARROS CENTRE, SINGAPORE 737869
Tel: (65)6844 3300/ (65)6545 3300 Fax: (65)6842 4988/ (65)6250 1284
Email: enquiry_autocare@thinkone.com.sg

ESTIMATED

Vehicle Plate No: YR2923H

Date: 09/10/2024

Make & Model: HINO XZU710R

Chassis No: JHHUCV3F70K057416

NO	PARTICULAR	QTY	UNIT/PRICE	AMOUNT S\$
1	SIDEGATE RH	1	R	3,500.00 X

LABOUR & MISCELLANEOUS:

- | | | | |
|---|--|--------|-----|
| 1 | To remove damaged body parts with all necessary components/attachments apply hot-works where necessary repair, reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments | 350.00 | 200 |
| 2 | To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials | 400.00 | 300 |

Not Authorized
in
morans
16/10/24
P/P \$500/
2 days.
Take photo After repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: