



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24100254/Anh3e2
75 BRAS BASAH ROAD	Date:	22/11/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMS 4541A	Veh. Inspected	SMX 2832Y
Policy No.	-	Coverage	0
Claim No.	MT/1299279-002	Excess	\$0.00
Assign From	ASTER QUEK	Assign Date	15/10/2024

2. Vehicle Details

Make & Model	TOYOTA C-HR	C.C	1797
Engine No.	2ZR2A09685	Year of Reg.	04/01/2021
Chassis No.	ZYX102126877	Colour	BLUE
Odometer	202120 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/60 R17	FIRENZA	6
L/H Front Tyre	215/60 R17	FIRENZA	6
R/H Rear Tyre	215/60 R17	FIRENZA	6
L/H Rear Tyre	215/60 R17	FIRENZA	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/10/2024	Inspection Date	15/10/2024 (13:01)
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days