



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE P1

1 GATEWAY DRIVE #15-08
WESTGATE TOWER
SINGAPORE 608531

TEL :

ATTN : ACCOUNTS DEPT

FAX :

YOUR REF NO : SMA2424M
CLAIM TYPE : THIRD PARTY
TP INS. CO. : ECICS LIMITED
ACCIDENT DATE : 30/09/2024
TP VEH REG NO : SMA2424M

ESTIMATE

NO

: QUOT202410-000028(00)

DATE

: 14/10/2024

POLICY NO

: SP2003907937

VEH REG NO

: SMK1312G

MAKE/MODEL

: MERCEDES BENZ GLB200
PROGRESSIVE

CHASSIS NO

: W1N2476872W072562

ENGINE NO

: 28291480389871

REG. DATE

: 2020

Not Notified
Repair B4 pain
4 days
86354.90

Estimate Repair Cost to Vehicle No : SMK1312G

Description	Quantity	Unit Price S\$	Amount S\$
NET PRICE			
1 Tailgate	1	2,295.00	2,295.00 ✓
2 Tailgate 'GLB200' emblem	1	103.00	103.00 ✓
3 Tailgate center logo	1	65.00	65.00 ✓
4 Rear end panel	1	3,118.00	3,118.00 X
5 Rear bumper	1	1,555.00	1,555.00 ✓
6 Rear bumper reinforcement	1	770.00	770.00 X
7 Rear bumper center inner frame	1	150.00	150.00 X
8 Rear bumper top chrome	1	270.00	270.00 ✓
9 Rear bumper lower garnish	1	283.00	283.00 X
10 Rear bumper lower chrome	1	1,578.00	1,578.00 ✓
11 Rear bumper sensor	2	216.00	432.00 X
12 Rear bumper sensor seals	6	12.00	72.00 ✓
13 Rear bumper clips	15	10.00	150.00 605
			10,841.00
		Less 10%	1,077.60
			9,763.40
SPECIAL NET			
14 Rear windscreen sealant	1	60.00	60.00 ✓
15 Tailgate " C&C emblem	1	38.00	38.00 ✓
			98.00
LABOUR			
16 To remove & refix rear windscreen	1	150.00	150.00 ✓
17 To transfer damaged tailgate interior parts to new tailgate	1	120.00	120.00 60
18 To remove & refit rear bumper sensor	1	100.00	100.00 60
19 To check & rectify wiring system	1	80.00	80.00 13
20 To remove & refix rear interior garnishes & trimboard to facilitate the repairs	1	180.00	180.00 X
21 To panel beat and straighten rear chassis frame, rear floorboard panel, to cut & weld rear end panel, including replacement of parts and align where necessary, to refit & adjust the same	1	1,200.00	1,200.00 4
22 To putty & spray paint on affected areas	1	1,000.00	1,000.00 44
23 To apply rust-proofing on replaced & repaired panels	1	120.00	120.00 ✓
			2,950.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE P1

1 GATEWAY DRIVE #15-08
WESTGATE TOWER
SINGAPORE 608531

TEL : FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SMA2424M
CLAIM TYPE : THIRD PARTY
TP INS. CO. : ECICS LIMITED
ACCIDENT DATE : 30/09/2024
TP VEH REG NO : SMA2424M

ESTIMATE

NO : QUOT202410-000028(01)
DATE : 22/10/2024
POLICY NO : SP2003907937
VEH REG NO : SMK1312G
MAKE/MODEL : MERCEDES BENZ GLB200
PROGRESSIVE
CHASSIS NO : W1N2476872W072562
ENGINE NO : 28291480389871
REG. DATE : 2020

Estimate Repair Cost to Vehicle No : SMK1312G

Description	Quantity	Unit Price	Amount
		S\$	S\$
SUPPLEMENTARY			
NET PRICE			
1 Taillamp assy - RH	1	458.00	458.00
2 Taillamp lower bracket - RH	1	590.00	590.00
			1,048.00
		Less 10%	104.80
			943.20
		TOTAL	S\$ 943.20
		ADD GST @ 9%	84.89
		GRAND TOTAL	S\$ 1,028.09

SINGAPORE DOLLAR ONE THOUSAND TWENTY-EIGHT AND CENTS NINE ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE