



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS SOMPO INSURANCE SINGAPORE PL	Ref:	CS/SMO24100260/Knp3m4
50 RAFFLES PLACE #03-03	Date:	29/10/2024
SINGAPORE LAND TOWER SINGAPORE 048623	Code:	SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMC 4737L	Veh. Inspected	SMH 1632Z
Policy No.	D24MTRENT000359	Coverage	0
Claim No.	CMTD2403326/GPL	Excess	\$0.00
Assign From	GNOH PAU LOONG	Assign Date	15/10/2024

2. Vehicle Details

Make & Model	TOYOTA COROLLA ALTIS (A)	C.C	1598
Engine No.	1ZRY241910	Year of Reg.	22/03/2016
Chassis No.	MR053REH104543341	Colour	METALLIC DARK GREY
Odometer	262964 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/55R16	ROAD X	6
L/H Front Tyre	205/55R16	ROAD X	6
R/H Rear Tyre	205/55R16	ROAD X	6
L/H Rear Tyre	205/55R16	ROAD X	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/10/2024	Inspection Date	16/10/2024
Survey held at	MASSIVE TRADING & AUTO - BLK 5038 ANG MO KIO INDUSTRIAL PARK 2 #01-405 SINGAPORE 569541		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days