

ASS. REC. BY:

REF:

Smo /

CS SMO 24 100260 / Knp3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

: Prell. Report

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel : 64817221

Kuah Bee Heong Baby Jane

Vehicle No : SMH 1632 Z
Make : Toyota Altis
Year : 2016

Not Withheld
61hr @ 3100h
Putty After Paint
3 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	X Rear boot lid			R	\$955.60	X	
1 pc	Rear boot lid - logo			na	\$55.10	✓	
1 pc	Rear boot lid emblem - Altis			na	\$65.70	✓	
1 pc	Rear boot lid emblem - Corolla			na	\$75.10	✓	
2 pcs	X Rear boot lid lamp ?		in	\$655.70	\$1,311.40	X	
1 pc	Rear boot rubber			in	\$205.60	X	
1 pc	X Rear end panel			R	\$685.70	X	
1 pc	Rear end panel inner garnish	? photo 166-20		na	\$263.70	✓	
1 pc	Rear n/s fender inner trim	? photo		Return / cm	\$487.50	✓	
1 pc	X Rear n/s fender			R	\$1,015.70	X	
1 pc	Rear n/s fender air duct	? photo		in	\$155.70	X	
2 pcs	Rear tail-lamp assy	? photo 0706-60		mg cm	\$750.60	\$1,501.20	✓
1 pc	Rear bumper			bu	\$687.60	✓	
1 pc	Rear bumper reinforcement	? photo		R	\$455.10	✓	
2 pcs	Rear bumper side retainer			\$95.10	D/I	\$190.20	✓
2 pcs	X Rear n/s bumper reflector			\$105.10	in	\$210.20	X
1 set	Rear reverse sensor	? photo		bu	\$395.10	2001	
					\$8,716.20		
					Less 25 %	\$2,179.05	
						\$6,537.15	

S Nett

20 pcs	Clip	\$2.00	na	\$40.00	—
--------	------	--------	----	---------	---

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.	\$1,200.00	400	
To putty & spray paint rear accident affected portion.	\$1,200.00	600	
Check/reconnect wiring.	\$45.00	20	
To spray anti rust on accident affected portion.	na	\$180.00	X
Total		<u>\$9,202.15</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: