

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel : 64817221

Kuah Bee Heong Baby Jane

Vehicle No : SMH 1632 Z
Make : Toyota Altis
Year : 2016

Not Withheld
61hr @ 3100p
Penny After Penny
3 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	✗ Rear boot lid	R	\$955.60	X
1 pc	Rear boot lid - logo	na	\$55.10	—
1 pc	Rear boot lid emblem - Altis	na	\$65.70	—
1 pc	Rear boot lid emblem - Corolla	na	\$75.10	—
2 pcs	✗ Rear boot lid lamp ?	in	\$655.70	\$1,311.40 X
1 pc	Rear boot rubber	in	\$205.60	X
1 pc	✗ Rear end panel	R	\$685.70	X
1 pc	Rear end panel inner garnish ? photo 168-20	na	\$263.70	—
1 pc	Rear n/s fender inner trim ? photo	Return / cm	\$487.50	—
1 pc	✗ Rear n/s fender	R	\$1,015.70	X
1 pc	Rear n/s fender air duct ? photo	in	\$155.70	X
2 pcs	Rear tail-lamp assy ? photo 0706-60	mg cm	\$750.60	\$1,501.20 —
1 pc	Rear bumper	Bu	\$687.60	—
1 pc	Rear bumper reinforcement ? photo	B	\$455.10	—
2 pcs	Rear bumper side retainer	\$95.10	DIT	\$190.20 —
2 pcs	✗ Rear n/s bumper reflector	\$105.10	in	\$210.20 X
1 set	Rear reverse sensor ? photo	Grled	\$395.10	2001
			\$8,716.20	
		Less 25 %	\$2,179.05	
			\$6,537.15	

S Nett

20 pcs	Clip	\$2.00	na	\$40.00 —
--------	------	--------	----	-----------

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.	\$1,200.00	400
To putty & spray paint rear accident affected portion.	\$1,200.00	600
Check/reconnect wiring.	\$45.00	20
To spray anti rust on accident affected portion.	na	\$180.00 X
Total	\$9,202.15	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: