

Llm Tien Siong

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:

Tokio Marine Insurance Singapore Ltd (HQ)

CTPL

Singapore

LKK-

45)

PARTICULARS OF CLAIM

Claim Type:	Third Party	Ref. No:	
Policy No:		Date of Loss:	15/10/2024
Vehicle Reg. No.:	SHD7309Z	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	04/12/2018
Vehicle Colour:	Blue	Gen Condition:	Good
Engine No:	G4LEJU132802	Chassis No:	KMHC851CVKU12202
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,335.32
Miscellaneous Items	12.00
Labour	1,400.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,747.32
+ GST 9.00% (S\$)	247.26
Nett Amount (S\$)	2,994.58

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

15/10 @ 16:34hrs.

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 15 Oct 2024)

Parts: 192 **HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's **(Price-denominated Standard List)**

Print Code: ComfortDelGro Engineering Pte Ltd/SHD7309Z/15/10/2024 16:34

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER	20.00	0.00	*481.10 FL <i>de</i>
2	1		*FRT BUMPER SIDE BRKT RH	20.00	0.00	*35.00 FL <i>X</i> nn
3	10		*FRT BUMPER CLIPS	20.00	0.00	*22.00 FL <i>ra</i>
4	1		*DAYLIGHT GRILLE RH	20.00	0.00	*93.45 FL <i>X</i> nn
5	1		*DAYLIGHT RH	20.00	0.00	*642.50 FL <i>X</i> nn
6	1		*FRT FENDER (BLUE-DRIVE) RH	20.00	0.00	*26.60 FL <i>de</i>
7	1		*FRT BUMPER UPPER MOULDING	20.00	0.00	*368.50 FL <i>X</i> nn

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	1,669.15
- List Item Discount on L Items (S\$)	333.83
Total Parts (S\$)	1,335.32

ComfortDelGro Engineering Pte Ltd/SHD7309Z/15/10/2024 16:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	12.00
Sub Total (S\$)			12.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING (FRONT FENDER RH)	New	380 800.00
2	SPRAY PAINTING	New	560 600.00
Gross Labour Cost (S\$)			1,400.00

ComfortDelGro Engineering Pte Ltd/SHD7309Z/15/10/2024 16:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanfli 97495419
'WP' 16/10/24 c 5pm
2 days
4/2 Repair after repair
tanfli c/branch in

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 16.10.2024 08:28

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5957699

JC NO305606495

CUSTOMER

/MS COMFORT TRANSPORTATION PTE LTD

CUSTOMER NO. 7010045

ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

Tel (R) 65508755

(O)

(P)

COUNT CARD NO.

REGN NO.:

SHD7309Z

MILEAGE

MAKE :

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G2)

15.10.2024 14:30

DATE/TIME IN

YR OF MANU.

04.12.2018

TARGET DATE

CHASSIS CODE

KMHC851CVKU122028

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 15.10.2024

NATURE: 3P 15.10.2024

S/NO LABOR CODE


000010

PB

000020

20-05

DESCRIPTION

LUMP SUM REPAIR-SHD7309Z-TP
TP MERIMEN

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHD7309Z

LIMITS

Vehicle No.:

SHD7309Z

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard