

QUAN DE MOTOR TRADING

1 KAKI BUKIT AVENUE 6, #01-67
AUTOBAY, SINGAPORE 417883
HP: 96709191

not Authorized
merci
16/10/24
d/s & 1600
the photo taken
2 days

AIG Asia Pacific Insurance Pte Ltd

Date: 16 October 2024

**Accident on 08/10/2024 involving vehicles PC7133Z & SNL3444D
along Marina Boulevard**

Estimate cost of repair to vehicle PC7133Z Mercedes V220D

Nett Items:

1 pc.	front bumper	Cn7	\$ 1,455.00	✓
1 pc.	front bumper beam	R	\$ 905.00	X
1 pc.	headlamp rh	Su	\$ 2,680.00	X
1 set	front bumper clips	ner	\$ 50.00	✓
1 pc.	front bumper PDC sensor	malfunction	\$ 215.00	✓
			<u>\$ 5,305.00</u>	
Less 10%			\$ 530.50	
			<u>\$ 4,774.50</u>	

Labour Charges:

To check wiring	\$ 50.00	20
To dismantle & replace front PDC sensor	\$ 50.00	30
To diagnostic & reprogramme system	✓ \$ 100.00	X
Labour for panel beating, welding and renew parts	\$ 380.00	200
Spray painting	\$ 500.00	220
Total:	<u>\$ 5,854.50</u>	

LKK Auto Consultants hence notify
the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) before survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: