

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	LIBERTY INSURAN	CE PTE LTD	Ref:	CS3/LIP24100271/Aqh3e2	
	ONE RAFFLES QUA SINGAPORE 04858	AY #25-01 NORTH TOWER	Date:	17/10/2024	
	MICAL CIVE 040303		Code:	LIP	
1.	Policy Particulars :- PRE-REPAIR SURVEY				
	Insured Veh.	GBG 897T	Veh. Inspected	SBM 35H	
	Policy No.	-	Coverage	0	
	Claim No.	AVS24/2768	Excess	\$0.00	
	Assign From	ANDY SEAH	Assign Date	16/09/2024	
2. Vehicle Details					
	Make & Model	MERCEDES BENZ E 200	c.c	1796	
	Engine No.	27186030485345	Year of Reg.	20/09/2012	
	Chassis No.	WDD2120482A632480	Colour	BROWN	
	Odometer	106653 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	225/45 R18	MICHELIN	6	
	L/H Front Tyre	225/45 R18	MICHELIN	6	
	R/H Rear Tyre	225/45 R18	MICHELIN	6	
	L/H Rear Tyre	225/45 R18	MICHELIN	6	
4.	Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5.		General Information			
	Accident Date	, ,			
	Survey held at	urvey held at MODERN AUTOMOTIVE PTE LTD - BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717			
5a. Remarks					
A) MARKET VALUE: \$92,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$60,089.00=NETT VALUE: \$31,911.00 B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. D) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. E) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000					

LWP

5b.

ADRIAN LING WAI PING

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days

Estimate Days of Repair