

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT/24100272/Uvh3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJQ 1528E
 at Workshop m/s Car Smith
 of _____
 Insured: SFP 8668R
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: 842k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 2 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS 386h
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SJQ 1528E Yr Regn: 27/04/09
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CAI
 Make: Toyota V105 c.c. 1497
 Colour: Beige A/C: Insured / Std / NI / NA
 Sp. Reading: 167174 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MR 0534493051 08956
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 185/60R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front _____ Rear 6
 R/Bal. 6 mm R/Bal. _____ mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 13/10/24 D.O.I. 16/10/24
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear O/S.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Dep 106</u>
	<u>COE uncl / 31-03-2029 LTA @ 11376</u>
	<u>Demges consistent OI/A report photo some as during survey</u>
	<u>quote \$800</u>
<u>18/10/24</u>	<u>L/S @ 1100 inform Alex</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: _____

1) _____
 Date/Time, File Return to?
 2) _____

Resurvey No. of Trip: _____

Survey Fee:	
Transportation: _____ S + RS, _____ SI	
Photos	
Others	
TOTAL	

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Report Format : _____
 Lump Sum / I.B.I: (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	386H
Vehicle Details	
Vehicle No.:	SJQ1528E
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Oct 2024
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS G AUTO
Primary Colour:	Beige
Manufacturing Year:	2009
Engine No.:	1NZX892880
Chassis No.:	MR053HY9305108956
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$13,472.00
Original Registration Date:	27 Apr 2009
First Registration Date:	27 Apr 2009
Transfer Count:	1
Actual ARF Paid:	\$13,472.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2029
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$25,525.00
COE Rebate Amount:	\$11,376.00
Total Rebate Amount:	\$11,376.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 16 Oct 2024

OK

CARSMITH PRIVATE LIMITED

PREMIER@8KAKI BUKIT AVE 4 #04-35 SINGAPORE415875

Tel: 9091 0000/ Email: info@carsmith.biz

NOT APPROVAL
 in
 memo
 16/10/24
 1/2 # 1100/
 2 days

VEHICLE NO: SJQ1528E

MAKE & MODEL: TOYOTA ALTIS

DOA: 13.10.2024

CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
REAR BUMPER (sport) 1100	1	\$ 1,235.30	De/Torn ✓
REAR BUMPER RETAINER LH	1	\$ 225.00	11 X
REAR BUMPER RETAINER RH	1	\$ 255.00	11 X
REAR BUMPER BRACKET LH	1	\$ 187.00	11 X
REAR BUMPER BRACKET RH	1	\$ 187.00	11 X
REAR END PANEL	1	\$ 955.00	11 X
END PANEL CENTRA BRACKET	2	\$ 320.00	11 X
REAR REINFORCEMENT	1	\$ 689.00	11 X
REAR BUMPER REFLECTOR LH	1	\$ 125.00	11 X
REAR BUMPER REFLECTOR RH	1	\$ 125.00	11 X
REAR LAMP LH	1	\$ 998.40	11 X
REAR LAMP BRACKET LH	1	\$ 225.00	11 X
REAR LAMP RH	1	\$ 998.40	11 X
REAR LAMP BRACKET RH	1	\$ 225.00	11 X
LOCK SENSOR	1	\$ 689.00	11 X
TAILGATE	1	\$ 2,251.00	11 X
TAILGATE RUBBER	1	\$ 328.50	11 X
TAILGATE WEATHERSTRIP	1	\$ 245.20	11 X
TAILGATE INNERLOCK	1	\$ 545.00	11 X
TAILGATE HINGE	2	\$ 285.00	11 X
TAILGATE EMBLEM	1	\$ 67.00	11 X
TAILGATE EMBLEM LOGO	1	\$ 55.00	11 X
TAILGATE GARNISH	1	\$ 141.00	11 X
REAR FENDER RH	1	\$ 1,754.00	11 X
REAR FENDER INNER SHIELD RH	1	\$ 275.00	11 X
		\$ 13,385.80	
	LESS 25%	\$ 3,346.45	
	SUB TOTAL	\$ 10,039.35	

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR BUMPER CLIP	1 SET	\$ 50.00	11 X
REAR NUMBER PLATE	1	\$ 90.00	11 X
REVERSE SENSOR	1 SET	\$ 480.00	11 X
REVERSE CAMERA	1	\$ 480.00	11 X
JOINT SEALANT	1	\$ 120.00	11 X
	SUB TOTAL	\$ 1,220.00	

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK ALL WIRING AND LIGHTING SYSTEM	1	\$ 240.00	20
REMOVE AND RENEW REAR REVERSE SENSOR	1	\$ 120.00	11 X

REMOVE AND REFIT REAR WINDSCREEN	1	\$ 240.00	11x
REMOVE AND REFIT FRONT AND REAR LINING, TRIM AND GARNISH	1	\$ 300.00	11x
PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	1	\$ 1,500.00	200
SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,500.00	350
APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 100.00	11x

SUB TOTAL \$ 4,000.00

GRAND TOTAL \$ 15,259.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2-1100
252

828
570

1398
202

1116.