

來發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No: EST0035945
GDI Container Trading Pte Ltd

Page: 1 of 3
Your ref.: TP-GBE 1526T ECICS
Job No.: 74766
Our ref: 24.10.12
Payment
Date: 15/10/2024

Attn

Vehicle No: SJN 9810C
Vehicle Model : Honda Fit
Accident on ...: 11/10/2024

NOT Authorized
11 Pp & 8350/h
Resurvey After Paint
14 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Rear bumper	980.70	20.00	Bn 784.56
1.00	Pc	Rear bumper towing cap	25.70	20.00	CM 20.56
1.00	Pc	Rear end panel	619.50	20.00	Bn 495.60
1.00	Pc	Rear end panel garnish	70.80	20.00	56.64
1.00	Pc	Rear end trim board RH <i>Rear trim board</i>	491.50	20.00	Bn 393.20
1.00	Pc	Rear fender RH	882.90	20.00	Bn 706.32
1.00	Pc	Rear tail lamp LH	261.10	20.00	WT 208.88
1.00	Pc	Rear tail lamp RH	261.10	20.00	Bn 208.88
1.00	Pc	Rear floor panel (centre)	823.50	20.00	BT/Bn 658.80
1.00	Pc	Rear chassis panel RH	687.60	20.00	Bn 550.08
1.00	Pc	Rear tail lamp panel RH	343.60	20.00	Bn 274.88
1.00	Pc	Rear side floor panel RH	171.30	20.00	Bn 137.04
1.00	Pc	Rear tailgate garnish	143.20	20.00	CM 114.56
1.00	Pc	Rear windscreen	652.90	20.00	Shatter 522.32
1.00	Pc	Rear windscreen rubber (upper)	43.50	20.00	Nn 34.80
1.00	Pc	Rear windscreen rubber (lower)	42.70	20.00	Nn 34.16
1.00	Pc	Rear fender glass rubber A	28.30	20.00	Nn 22.64
1.00	Pc	Rear fender glass rubber B	37.50	20.00	Nn 30.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____

本公司拥有最先进的 CAROLINER MARK IV 机械，
除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

來發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0035945
GDI Container Trading Pte Ltd

Page 2 of 3
Your ref. TP-GBE 1526T ECICS
Job No. 74766
Our ref 24.10.12
Payment
Date 15/10/2024

Attn

Vehicle No: SJN 9810C
Vehicle Model : Honda Fit
Accident on ...: 11/10/2024

Quantity	Unit	Description	Unit price	Disc. pct.	Amount	
			234.70	20.00	187.76	✓
1.00	Pc	Rear tailgate lock	35.30	20.00	28.24	X
1.00	Pc	Rear tailgate striker	92.30	20.00	73.84	5092
1.00	Pc	Rear tailgate weatherstrip rubber	58.30	20.00	46.64	2
1.00	Pc	Rear tailgate wiper blade	258.60	20.00	206.88	X
1.00	Pc	Rear tailgate wiper motor	1,042.10	20.00	833.68	✓
1.00	Pc	Rear tailgate	365.90	20.00	292.72	✓
1.00	Pc	Rear end "box"	3.00	20.00	14.40	✓
6.00	Pcs	Rear bumper lower clips	21.50	20.00	17.20	✓
1.00	Pc	Rear bumper outer retainer RH				
Special Netti Items:						
1.00	Pc	Rear bumper lower spoiler (Aftermarket)	250.00		250.00	✓
1.00	Set	Reverse sensor c/w installation	200.00		200.00	✓
1.00	Pc	Rear number plate	40.00		40.00	✓
1.00	Pc	Rear windscreen sealant	60.00		60.00	4092
1.00	Pc	Side glass sealant RH	40.00		40.00	✓
1.00	Pc	Rear windscreen seal	30.00		30.00	✓

Labour & Misc:

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

來發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0035945
GDI Container Trading Pte Ltd

Page 3 of 3
Your ref. TP-GBE 1526T ECICS
Job No. 74766
Our ref 24.10.12
Payment
Date 15/10/2024

Attn

Vehicle No SJN 9810C
Vehicle Model : Honda Fit
Accident on ... 11/10/2024

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To cut+weld; to straighten rear chassis+renew above parts	1,800.00		1,800.00 <i>1600</i>
1.00		To transfer reverse camera+parts	60.00		60.00 ✓
1.00		To remove+install rear windscreen including rear side glass RH	250.00		250.00 <i>180</i>
1.00		To remove+refix rear seat+trim board for repairing	250.00		250.00 <i>120</i>
1.00		Tuff coat+underbody anti-rust	150.00		150.00 <i>120</i>
1.00		To dismantle+refix rear exhaust muffler+heat shield etc	60.00		60.00 ✓
1.00		To respray paint rear tailgate, rear fender RH, rear bumper, rear end panel, rear end floor panel etc	1,600.00		1,600.00 <i>1400</i>
Sub-Total					11,745.28
GST 9.00%					1,057.08
Total					S\$ 12,802.36

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."