

CHIA AUTO SERVICES PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6243 1373

Reg. No: 201538764H

CA3SERVICES@GMAIL.COM

ATTENTION:	MOTOR CLAIMS DEPARTMENT
DATE:	17-10-24
CLAIM TYPE:	T/P CLAIM
TO:	SOMPO
VEHICLE DETAILS	
VEHICLE NO:	GBG2519Y
MAKE & MODEL:	TOYOTA HIACE
CHASSIS NO:	
ACCIDENT DETAILS	
DATE:	1 October, 2024
TIME:	1505HRS
THIRD PARTY REQUESTOR:	JACK LI

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	SLIDING DOOR LH <i>Repair</i>	1	\$ 2,955.30	\$ 2,955.30
2	REAR FENDER LH <i>Distorted</i>	1	\$ 2,877.20	\$ 2,877.20
3	REAR RAILWAY PANEL <i>Best</i>	1	\$ 890.00	\$ 890.00
4	REAR RAILWAY PANEL END ?	1	\$ 160.00	\$ 160.00
5	TAILLAMP LH ?	1	\$ 350.00	\$ 350.00

TOTAL PRICE \$ 7,232.50

LESS 25% \$ 1,808.13

SUB TOTAL PRICE \$ 5,424.38

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 1,200.00	\$ 1,200.00
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 1,200.00	\$ 1,200.00
3	TUFF COAT	1	\$ 200.00	\$ 200.00
4	WIRING CHECK	1	\$ 80.00	\$ 80.00
5	REMOVE AND REFIX FRONT DOOR MECHANISM	1	\$ 120.00	\$ 120.00

TOTAL \$ 2,800.00

ESTIMATE REPORT

TOTAL PARTS COST \$ 5,424.38

TOTAL LABOUR COST	\$	2,800.00
TOTAL REPAIR COST	\$	8,224.38

APPROVED DETAILS:

SURVEYOR:

CONTACT NO.:

PART BY PART/LUMP SUM

NO. OF DAYS

Adnan
1/s 17/10/24
05 hrs.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: