

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24100275/APA3Q2**Date:** 17/01/2025REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7220035844
Claimant Vehicle No : SJE6724K **Insured Vehicle No :** SKS9306D
 Date of Loss: 07/10/2024 Nature of Claim: TP Claim No: 2330182994SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJE6724K**
 Make & Model: TOYOTA ESTIMA, 2.4 (A) Engine No: 2AZF137889
 Reg. Date: 02/05/2008 (Man. Year: 2008) Chassis No: ACR500068712
 Colour: Silver Odometer: 280951 km
 Engine Capacity: 2362 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
 Front Left Side: Tourador 6 mm Rear Left Side: Tourador 6 mm
 Front Right Side: Tourador 6 mm Rear Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,896.10	1,835.90	4,060.20	68.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	1,370.00	1,570.00	53.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,836.10	3,205.90	5,630.20	63.72
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	8,836.10	2,500.00	6,336.10	71.71
+ GST 9.00/9.00% (S\$)	795.25	225.00	570.25	71.71
Nett Amount (S\$)	9,631.35	2,725.00	6,906.35	71.71
+ Car Rental (4.0 x S\$100.00/day + 9.00% GST) (S\$)		436.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		3,188.25		

INSPECTION

Date of Assignment: 15/10/2024
 Date Inspected: 15/10/2024 Inspected At: Xin Hua Workshop Pte Ltd (HQ)
 23 Kaki Bukit Ave 4 #04-01
 Singapore 415933
 Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	1,645.80 FL	*- FL
2	1		*TAILGATE WINDSCREEN MOULDING	Not Necessary	171.10 FL	*- FL
3	1		*TAILGATE BADGE	Necessary	95.20 FL	*95.20 FL
4	1		*TAILGATE EMBLE ESTIMA	Necessary	94.60 FL	*94.60 FL
5	1		*TAILGATE EMBLEM X	Necessary	93.80 FL	*93.80 FL
6	1		*TAILGATE INNER TRIMS	Not Necessary	581.10 FL	*- FL
7	1		*TAILGATE INNER LOCK	Not Necessary	459.50 FL	*- FL
8	1		*TAILGATE LOCK CATCH	Not Necessary	61.10 FL	*- FL
9	1		*TAILGATE WEATHERSTRIP	Not Necessary	329.60 FL	*- FL
10	1		*REAR BUMPER	Deformed	1,245.80 FL	*825.00 FL
11	1		*REAR BUMPER SIDE RETAINERS	Not Necessary	131.80 FL	*- FL
12	1		*REAR BUMPER ATTACHMENT RETAINERS	Not Necessary	121.30 FL	*- FL
13	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
14	1		*REAR BUMPER KEY ANTENA SENSOR	Not Necessary	185.20 FL	*- FL
15	1		*REAR BUMPER SIDE SPONGE	Not Necessary	263.20 FL	*- FL
16	1		*REAR BUMPER REFLECTOR	Not Necessary	83.40 FL	*- FL
17	1		*REAR BUMPER TOW COVER	Not Necessary	43.90 FL	*- FL
18	1		*TAILLAMP LH	Not Necessary	492.80 FL	*- FL
19	1		*TAILLAMP INNER SEALER	Not Necessary	38.00 FL	*- FL
20	1		*SET TAILLAMP CLIPS	Not Necessary	25.00 FL	*- FL
21	1		*END PANEL OUTER	Dented	656.00 FL	*656.00 FL
22	1		*END PANEL TOP TRIM	Deformed	286.60 FL	*286.60 FL
23	1		*REAR NUMBER PLATE WITH HOLDER	Not Necessary	70.00 FS	*- FS
24	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
25	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
26	1		*SET BODY PANEL JOINT SEALANT	Necessary	120.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,684.80	2,361.20
- List Item Discount on L Items 25.00/25.00% (\$)	1,788.70	525.30
Total Parts (\$)	5,896.10	1,835.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	600.00
2	SPRAY PAINTING	New	1,200.00	600.00
3	CHECK WIRING ON TAILAMP	New	80.00	0.00
4	ANTI RUST	New	100.00	60.00
5	REMOVE AND INSTALL REAR WINDSCREEN	New	120.00	0.00
6	REMOVE AND INSTALL TAILGATE PARTS	New	120.00	60.00
7	REMOVE AND INSTALL REVERSE SENSOR	New	120.00	50.00
Gross Labour Cost (\$\$)			2,940.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >