

Not Authored  
L1 Sm & 3950/r

**Trans-cab Auto Services Pte Ltd**

AAD2410-052

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD5146P**

Vehicle No.:  
Chassis No.:  
Co UEN:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :  
Date of Registration :

**SHD5146P**

JTDKB3FU503076410  
200303878K  
TOYOTA  
PRIUS  
15/10/2024  
**SLH5963D/ECICS**  
1/11/2018

- PART**
- 1 COVER, FRONT BUMPER
  - 1 ABSORBER, FRONT BUMPER ENERGY
  - 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
  - 1 STAY SUB-ASSY, FRONT BUMPER, LH
  - 1 BRACKET, FRONT BUMPER SIDE, LH
  - 1 COVER, FRONT BUMPER HOLE, LH
  - 1 COVER SUB-ASSY, FRONT PILLAR, UPR LH
  - 1 SUPPORT, RADIATOR, UPPER LH
  - 1 HOOD SUB-ASSY
  - 1 HINGE ASSY, HOOD, LH
  - 1 HINGE ASSY, HOOD, RH
  - 1 LAMP ASSY, FOG, LH
  - 1 UNIT ASSY, HEADLAMP, LH
  - 1 FENDER SUB-ASSY, FRONT LH
  - 1 EMBLEM, SIDE PANEL LH
  - 1 LINER, FRONT FENDER, LH

	<b>LIST</b>	
\$	<i>Bot</i> 653.31	✓
\$	<i>CM</i> 100.17	✓
\$	<i>R</i> 902.16	X
\$	<i>R</i> 59.85	X
\$	<i>Dit</i> 74.97	✓
\$	<i>Mit</i> 37.07	✓
\$	<i>R</i> 126.74	X
\$	<i>R</i> 99.33	X
\$	<i>R</i> 1,243.20	X
\$	<i>R</i> 74.34	X
\$	<i>R</i> 74.34	X
\$	<i>M3 CM</i> 1,200.78	✓
\$	<i>M3 CM</i> 3,325.56	✓
\$	<i>R</i> 1,236.69	X
\$	<i>R</i> 68.88	✓
\$	<i>R</i> 255.36	X
<b>TOTAL</b> \$	<b>9,532.74</b>	
<b>25%</b> \$	<b>2,383.19</b>	
\$	<b>7,149.56</b>	

**Special Nett**

- 1 FRT BUMPER CLIP \$ *Na* 65.00 *60.00*
- 1 FENDER LINER CLIP \$ *na* 130.00 X

**Trans-cab Auto Services Pte Ltd**

AAD2410-052

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD5146P**

1 FRT LH BUMPER RETAINER CLIP

\$	<i>nn</i>	65.00	X
<b>\$</b>		<b>260.00</b>	

**TOTAL**

<b>TOTAL PARTS</b>	<b>\$</b>	<b>7,409.56</b>
--------------------	-----------	-----------------

**LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	<i>nn</i>	380.00	X
----	-----------	--------	---

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$		1,400.00	<i>3501</i>
----	--	----------	-------------

Putty And Spray Painting Of The Affected Portion.

\$		1,400.00	<i>4401</i>
----	--	----------	-------------

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$	<i>nn</i>	240.00	X
----	-----------	--------	---

To Check Electrical Lighting Concerned.

\$		170.00	<i>201</i>
----	--	--------	------------

<b>TOTAL</b>	<b>\$</b>	<b>3,590.00</b>
--------------	-----------	-----------------

<b>Over All Total</b>	<b>\$</b>	<b>10,999.56</b>
-----------------------	-----------	------------------

**(PART-BY-PART) Repair Days**~~06~~ days*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: