

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0492/2024/KS
DATE : 25-Jun-24
WIP : 20613

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 5/4/2024

YOUR INSURED VEH NO : SNL 6622 L

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Hi Adrian,

4 Days - OK - Allan Boo

19-Aug-24

OWNER'S NAME : MS SRISAHTI CHHABRA
ADDRESS : 20 JALAN HAJIJAH
#02-03
SINGAPORE 468726
TELEPHONE : HP +65 98444379
TYPE OF CLAIM : OWN DAMAGE CLAIMS
POLICY NO : 5114240297-04
VEHICLE NO : **SMQ 7536 G**
MODEL CODE : AUDI A3 SPORTSBACK 1.0
MODEL YEAR : 29/11/2019
ENGINE NO : CHZ C32621
CHASSIS NO : WAUZZZ8V0KA117900
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Jun-24
PLACE OF ACCIDENT : NEWTON CIRCUS

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMQ 7536 G.

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS	
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00		
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	S/N \$	350.00	\$	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	\$	1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$	1,800.00	\$	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	\$	292.00
TOTAL LABOUR CHARGES		:	\$ 4,902.00	\$	2,642.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 7536 G.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,411.00	\$ 1,928.80
2	FRONT BUMPER FIXING PARTS	1	\$ 209.00	
3	FRONT BUMPER GUIDE SECTION - RH	1	\$ 49.00	\$ 38.56
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 373.00	
5	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 357.00	
6	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 236.00	
7	FRONT FENDER - RH	1	\$ 1,016.00	\$ 812.80
8	FRONT FENDER ATTACHMENT PARTS - RH	1	\$ 85.00	
9	FRONT FENDER BRACKET - RH REAR	1	\$ 45.00	
10	FRONT FENDER BRACKET - RH FRONT	1	\$ 74.00	
11	FRONT FENDER RIVET - RH	8	\$ 34.00	
12	FRONT FENDER SEAL - RH	1	\$ 43.00	
13	FRONT FENDER BRACE - RH	1	\$ 122.00	\$ 97.20
14	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 76.00	\$ 60.80
15	FRONT WHEEL HOUSING LINER - RH	1	\$ 204.00	
16	WHEEL HOUSING LINER ATTACHMENT PARTS- RH	1	\$ 67.00	
17	LED HEADLIGHT - RH	1	\$ 6,647.00	\$ 5,317.60
18	LIFT CYLINDER - RH	1	\$ 170.00	
19	LIFT CYLINDER HOSE - RH	1	\$ 86.00	
20	SUNDRIES		\$ 500.00	\$ 26.88
TOTAL SPARE PARTS		:	\$ 12,804.00	\$ 8,282.64
TOTAL LABOUR CHARGES		:	\$ 4,902.00	\$ 2,642.00
GRAND TOTAL		:	\$ 17,706.00	\$ 10,924.64

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT