
PREMIUM AUTOMOBILES



Xian Tory

55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE

ACCIDENT REPAIRS

WORKSHOP

UBI ROAD 1

CONTACT NO

6366 2323

FAX NO

6841 1183

REFERENCE

PA/TP/0492/2024/KS

DATE

25-Jun-24

WIP

20613

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 5/4/2024 YOUR INSURED VEH NO: SNL 6622 L

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME

MS SRISAHTI CHHABRA

ADDRESS

20 JALAN HAJIJAH

#02-03

SINGAPORE 468726

TELEPHONE

: HP +65 98444379

TYPE OF CLAIM

OWN DAMAGE CLAIMS

POLICY NO

5114240297-04

VEHICLE NO

SMQ 7536 G

MODEL CODE

: AUDI A3 SPORTSBACK 1.0

WAUZZZ8V0KA117900

MODEL YEAR

29/11/2019

ENGINE NO

CHZ C32621

CHASSIS NO MILEAGE

DATE IN

ESTIMATED BY

: JOHNNY BOO / ALLAN WU

ACCIDENT DATE

: 24-Jun-24

PLACE OF ACCIDENT

: NEWTON CIRCUS

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183 EMAIL NORA KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMQ 7536 G.

S/N	NATURE OF JOBS	****	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N	\$ 360.00	*
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	S/N	\$ 350,00	257 /
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$	1000
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.		\$ 1,800.00	1102 /
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 292.00	/ /
	TOTAL LABOUR CHARGES	:	\$ 4,902.00	

* PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183 EMAIL NORA KHAI@PREMIUMAUTO COM SG / CLAIMS@PREMIUMAUTO COM SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 7536 G.

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
1	FRONT BUMPER Della	1	s	2,411.00	1,928.80
2	FRONT BUMPER FIXING PARTS	1	\$	209.00	1
3	FRONT BUMPER GUIDE SECTION - RH	1	\$	49.00	√ 38.56
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$	373.00	4
5	FRONT BUMPER CLOSING ELEMENT - RH	1	\$	357.00	4
6	FRONT BUMPER AIR GUIDE GRILLE - RH	1	S	236.00	+
7	FRONT FENDER - RH Derted	1	\$	1,016.00	¥812.80
8	FRONT FENDER ATTACHMENT PARTS - RH	1	S	85.00	+
9	FRONT FENDER BRACKET - RH REAR	1	\$	45.00	NN X°
10	FRONT FENDER BRACKET - RH FRONT	1	S	74.00	XNN
11	FRONT FENDER RIVET - RH	8	\$	34.00	X NN
12	FRONT FENDER SEAL - RH	1	\$	43.00	XNN
13	FRONT FENDER BRACE - RH V BT	1	\$	122.00	√ 97.20
14	FRONT FENDER CLOSING ELEMENT - RH DAMAGED	1	\$	76.00	√ 60.80
15	FRONT WHEEL HOUSING LINER - RH	1	\$	204.00	4
	WHEEL HOUSING LINER ATTACHMENT PARTS- RH	1	\$	67.00	+
16	LED HEADLIGHT - RH	1	\$	6,647.00	√ 5,317.60
17	LIFT CYLINDER - RH 2.	1	\$	170.00	+
17.70	LIFT CYLINDER HOSE - RH	1	\$	86.00	*
19			S		V 26.88
20	SUNDRIES				_
	TOTAL SPARE PARTS	:	\$	12,804.00	
	TOTAL LABOUR CHARGES	;	\$	4,902.00	
	GRAND TOTAL	:	\$	17,706.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183 EMAIL NORA KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE **AUTHORISED DATE EXCESS COST**

LIABILITY

REMARKS

Adrin () 28/06/24

he Authorised, 04 Pags St.

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR

APPOINTMENT.

YOURS FAITHFULLY, PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following: . To resurvey beforefafter spray soming To display demaged parts) (burns resurvey * Parts prices are subject to cast (must on * Third party survey is on a "Victorial Psepudoe" basis No liegal modulcation(s) is not seen. Supplementary remain must be uncovered and is subject to light applical high insurance can Acknowledged by Repairer. Signatures

JOHNNY BOO BODY REPAIR MANAGER ALLAN WU CLAIMS CONSULTANT