

# JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit  
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778  
E-mail:jlperfectautowork@gmail.com



DATE : 14.10.2024

TO : CHINA TAIPING MOTOR CLAIMS DEPTS  
VEHICLE NO : GBD9119M  
MODEL : TOYOTA HIACE  
DATE OF ACCIDENT : 14.10.2024  
TIME OF ACCIDENT : 13:15 HOURS

Daphne.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

## CLAIM DETAIL : PARTS

| S/N | DESCRIPTION                                | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|--------------------------------------------|-----|-----------------|------------------|
| 1   | TAILGATE <i>Dented</i>                     | 1   | \$ 2,210.70     | \$ 2,210.70      |
| 2   | TAILGATE OUTER MOULDING <i>new</i>         | 1   | \$ 364.90       | \$ 364.90        |
| 3   | TAILGATE OUTER HANDLE <i>new</i>           | 1   | \$ 97.80        | \$ 97.80         |
| 4   | TAILGATE NUMBER PLATE LAMP <i>new</i>      | 2   | \$ 65.50        | \$ 131.00        |
| 5   | TAILGATE LOGO <i>new</i>                   | 1   | \$ 70.50        | \$ 70.50         |
| 6   | TAILGATE REVERSE CAMERA <i>new</i>         | 1   | \$ 894.20       | \$ 894.20        |
| 7   | TAILGATE CORNER GARNISH <i>LH cracked</i>  | 2   | \$ 185.90       | \$ 371.80        |
| 8   | TAILGATE STOPPER (UPPER SIDE) <i>new</i>   | 2   | \$ 24.10        | \$ 48.20         |
| 9   | TAILGATE SIDE STOPPER (LOWER) <i>new</i>   | 2   | \$ 28.60        | \$ 57.20         |
| 10  | TAILGATE INNER BOARD <i>torn</i>           | 1   | \$ 388.70       | \$ 388.70        |
| 11  | TAILGATE WEATHERSTRIP <i>torn</i>          | 1   | \$ 397.80       | \$ 397.80        |
| 12  | TAILGATE WEATHERSTRIP PROTECTOR <i>new</i> | 1   | \$ 271.60       | \$ 271.60        |
| 13  | TAILGATE INNER LOCK <i>new</i>             | 1   | \$ 354.60       | \$ 354.60        |
| 14  | TAILGATE LOCK MOTOR <i>new</i>             | 1   | \$ 545.00       | \$ 545.00        |
| 15  | TAILGATE LOWER LOCK <i>new</i>             | 1   | \$ 254.10       | \$ 254.10        |
| 16  | TAIL LAMP <i>LH cracked</i>                | 2   | \$ 355.20       | \$ 710.40        |
| 17  | TAIL LAMP PANEL LH <i>new</i>              | 1   | \$ 419.80       | \$ 419.80        |
| 18  | TAILLAMP LOWER GARNISH <i>LH cracked</i>   | 2   | \$ 257.40       | \$ 514.80        |
| 19  | TAILLAMP LOWER GARNISH RETAINER <i>new</i> | 2   | \$ 53.70        | \$ 107.40        |
| 20  | REAR SIDE PANEL LH <i>new</i>              | 1   | \$ 1,828.90     | \$ 1,828.90      |
| 21  | REAR SIDE PANEL AIR VENT LH <i>new</i>     | 1   | \$ 185.70       | \$ 185.70        |



TO : CHINA TAIPING MOTOR CLAIMS DEPTS  
 VEHICLE NO : GBD9119M  
 MODEL : TOYOTA HIACE  
 DATE OF ACCIDENT : 14.10.2024  
 TIME OF ACCIDENT : 13:15 HOURS

|    |                                          |   |             |             |   |
|----|------------------------------------------|---|-------------|-------------|---|
| 22 | REAR BUMPER <i>Dehnd</i>                 | 1 | \$ 497.00   | \$ 497.00   | - |
| 23 | REAR BUMPER SIDE RETAINER <i>ren</i>     | 2 | \$ 47.50    | \$ 95.00    | + |
| 24 | REAR END PANEL (EXTEND) <i>LH Dented</i> | 1 | \$ 428.10   | \$ 428.10   | ✓ |
| 25 | REAR END PANEL (INNER) <i>Reps</i>       | 1 | \$ 1,124.80 | \$ 1,124.80 | + |
| 26 | REAR END PANEL (OUTER) <i>Dented</i>     | 1 | \$ 498.60   | \$ 498.60   | ✓ |
| 27 | REAR FLOOR PANEL <i>Reps</i>             | 1 | \$ 1,966.20 | \$ 1,966.20 | + |
| 28 | REAR FLOOR PANEL MAT <i>ren</i>          | 1 | \$ 1,215.10 | \$ 1,215.10 | - |

5833.90  
 4380.42

TOTAL PRICE \$ 16,049.90  
 LESS 25% \$ 4,012.48  
**SUB TOTAL PRICE \$ 12,037.43**

| S/N | DESCRIPTION                                                | QTY | UNIT S/NETT | TOTAL S/NETT |     |
|-----|------------------------------------------------------------|-----|-------------|--------------|-----|
| 1   | REAR NUMBER PLATE <i>ren</i>                               | 1   | \$ 50.00    | \$ 50.00     | 30  |
| 2   | REAR BUMPER CLIP (SET) <i>ren</i>                          | 1   | \$ 50.00    | \$ 50.00     | 30  |
| 3   | REAR SIDE PANEL SEALANT (OUTER) <i>ren</i>                 | 2   | \$ 150.00   | \$ 300.00    | +   |
| 4   | TAIL LAMP CLIP (SET) <i>ren</i>                            | 1   | \$ 30.00    | \$ 30.00     | +   |
| 5   | TAILLAMP LOWER GARNISH CLIP (SET) <i>ren</i>               | 1   | \$ 30.00    | \$ 30.00     | 20  |
| 6   | TAILGATE SEALANT <i>ren</i>                                | 1   | \$ 150.00   | \$ 150.00    | +   |
| 7   | TAILGATE OUTER MOULDING CLIP (SET) <i>ren</i>              | 1   | \$ 50.00    | \$ 50.00     | +   |
| 8   | TAILGATE TOP TRIM CLIP (SET) <i>ren</i>                    | 1   | \$ 50.00    | \$ 50.00     | +   |
| 9   | TAILGATE INNER TRIM CLIP (SET) <i>ren</i>                  | 1   | \$ 50.00    | \$ 50.00     | 30  |
| 10  | TAILGATE STICKER '70KM/H' <i>New</i>                       | 1   | \$ 30.00    | \$ 30.00     | 15  |
| 11  | TAILGATE WINDSCREEN SEALANT <i>2 ren</i>                   | 1   | \$ 80.00    | \$ 80.00     | 40  |
| 12  | TAILGATE WINDSCREEN INNER SEAL <i>1</i>                    | 1   | \$ 60.00    | \$ 60.00     | 30  |
| 13  | REAR END PANEL (OUTER) SEALANT <i>ren</i>                  | 1   | \$ 150.00   | \$ 150.00    | 60  |
| 14  | REAR END PANEL (EXTEND) SEALANT <i>ren</i>                 | 1   | \$ 150.00   | \$ 150.00    | +   |
| 15  | REAR FLOOR PANEL TOP COVER (BOARD) SPECAIL TYPE <i>ren</i> | 1   | \$ 800.00   | \$ 800.00    | +   |
| 16  | REAR STICKER (SPECAIL TYPE) <i>Nec</i>                     | 1   | \$ 400.00   | \$ 400.00    | 120 |

375

**TOTAL \$ 2,430.00**

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

| S/N | JOB DESCRIPTION                 | PRICE       | ADJUSTED COST |
|-----|---------------------------------|-------------|---------------|
| 1   | PANEL BEATING AND REPLACE PARTS | \$ 2,400.00 | <i>800</i>    |



TO : CHINA TAIPING MOTOR CLAIMS DEPTS  
 VEHICLE NO : GBD9119M  
 MODEL : TOYOTA HIACE  
 DATE OF ACCIDENT : 14.10.2024  
 TIME OF ACCIDENT : 13:15 HOURS

|    |                                                                                                      |             |     |
|----|------------------------------------------------------------------------------------------------------|-------------|-----|
| 2  | SPRAY PAINTING TO AFFECTED AREA                                                                      | \$ 2,000.00 | 700 |
| 3  | WIRNING, BULB CHECKING                                                                               | \$ 80.00    | 30  |
| 4  | TRANSFER TAILGATE MECHAISM                                                                           | \$ 80.00    | 60  |
| 5  | CONDUCT WATER LEAKAGE TEST                                                                           | \$ 120.00   | x   |
| 6  | REMOVE AND REFIX ROOF LINING                                                                         | \$ 100.00   | +   |
| 7  | REMOVE AND REFIX FUEL TANK                                                                           | \$ 100.00   | +   |
| 8  | REMOVE AND REFIX REAR FLOOR BAORD                                                                    | \$ 350.00   | x   |
| 9  | REMOVE AND REFIX REVERSE CAMERA                                                                      | \$ 120.00   | 50  |
| 10 | REAR CHASSIS ALIGHMENT                                                                               | \$ 250.00   | x   |
| 11 | REMOVE AND REFIX REAR WINDSCREEN                                                                     | \$ 120.00   | ✓   |
| 12 | TO CHECK DIAGNOSTICS OF VEHICLE<br>MANAGEMENT/CONTROL UNITS, RESET<br>MEMORIES TO SPECIFICATION ETC. | \$ 180.00   | x   |

TOTAL \$ 5,900.00

#### ESTIMATE REPORT

TOTAL PARTS COST : \$ 14,467.43  
 TOTAL LABOUR COST : \$ 5,900.00  
 TOTAL REPAIR COST : \$ 20,367.43

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

**PARTS PRICES ARE SUBJECT TO CHANGES.**

YOURS FAITHFULLY,

**IRENE**

SERVICE ADVISOR  
 IRENE  
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Cj  
 1/5 15/10/24

06 Days.

blul: 652592  
 1/5 5.21c ✓

1760