

ASS. REC. BY:

REF:

C121 CS/CTI24100279/Kvh3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

SNM 4462P

Policy No.

Claims No.

SNM24D205761

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

823K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SK 7 204L

Yr Regn:

01.16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia Corolla Park C.O. 1591

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading

150314

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNAF 8 411 m.v. = 5532878

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Nexen

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

13/10/24

D.O.I.

16/10/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/10

21/10 @ 6250h Colm

(red 6637.36, 51%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 116C

Vehicle Details

Vehicle No.: SKZ204L
Vehicle to be Exported: No
Intended Deregistration Date: 14 Oct 2024
Vehicle Make: KIA
Vehicle Model: FORTE K3 1.6A SX
Primary Colour: Red
Manufacturing Year: 2015
Engine No.: G4FGFH799161
Chassis No.: KNAFZ411MF5532878
Maximum Power Output: 95.3 kW (127 bhp)
Open Market Value: \$16,995.00
Original Registration Date: 06 Jan 2016
First Registration Date: 06 Jan 2016
Transfer Count: 1
Actual ARF Paid: \$16,995.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 05 Jan 2026
PARF Rebate Amount: \$9,347.00

Intended COE Rebate Details

COE Expiry Date: 05 Jan 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$56,989.00
COE Rebate Amount: \$6,985.00
Total Rebate Amount: \$16,332.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 14 Oct 2024

OK

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

Not Authorized
L1 Sup & 8250/r
Returning After Pain
6days

To: China Taiping Insurance (S) Pte Ltd

Policy No: _____ Third Party

Date: _____ 15.10.2024

Accident Date : 13.10.2024

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Kia Cerato Forte K3" Reg. No. SKZ204L Claiming Against Your Insured Veh. No. SNM4462P			
1pc	Boot	203.00	By 1,385.00 ✓
2pcs	Boot Hinges		na 406.00 X
1pc	Boot Emblem		na 104.00 ✓
1pc	Boot Lock 169		na 253.00 ✓
1pc	Boot Lock Catch	82.505A	na 39.00 X
1pc	Boot Weatherstrip 165		na 305.00 505A
1pc	Boot Badge (Forte)		na 115.00 ✓
1pc	Boot Badge K3		na 85.00 ✓
1pc	Boot Trim Board 183		CM 295.00 ✓
11pcs	Boot Trim Board Clips	3.80	na 41.80 ✓
1pc	Boot Drain Stopper		na 12.00 ✓
1pc	Boot Key Sensor		CM 245.00 ✓
1pc	Rear Bumper 65P		na 849.00 ✓
12pcs	Rear Bumper Clips	3.80	na 45.60 ✓
2pcs	Rear Bumper Brackets	165.00	By 330.00 ✓
1pc	Rear Bumper Reinforcement 315		CM 455.00 ✓
2pcs	Rear Bumper Top Retainers	76.00	na 152.00 X
1pc	Rear Bumper Lower Diffuser Cover		na 350.00 ✓
2pcs	Rear Bumper Reflectors 065-90	155.00	na 310.00 ✓
2pcs	Rear Bumper Sensors 017A	mis/shut 259.00	na 518.00 ✓
4pcs	Rear Bumper Sensor Holders	55.00	na 220.00 X
1pc	Rear Bumper Sensor Wiring Harness 323		na 650.00 ✓
2pcs	Rear Bumper Corner Retainers	85.00	na 170.00 ✓
3pcs	Rear Bumper Lower Holders	55.00	na 165.00 X
3pcs	Rear Bumper Lower Cover	215.00	na 645.00 X
1pc	End Panel 480.50		na 735.00 X
1pc	End Panel Garnish	cl/serm 320.00	na 225.00 ✓
2pcs	Rear Fender Trim Boards		na 640.00 ✓
1pc	Spare Tyre Top Board		na 360.00 ✓
1pc	Rear Exhaust Finisher		na 975.00 X
Less 10%			11,080.40
			1,108.04
			9,972.36
Boot Badge C&C			na 55.00 SN ✓
Road Side Assist Signage			na 120.00 SN ✓
Portable Tyre Inflator			na 350.00 SN X
To Dismantle / Transfer Boot Fittings / Ancillary Accessories			150.00 601
C/F			10,647.36

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

To: China Taiping Insurance (S) Pte Ltd

Policy No: Third Party

Date: 15.10.2024

Accident Date : 13.10.2024

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Kia Cerato Forte K3" Reg. No. SKZ204 Claiming Against Your Insured Veh. No. SNM4462P		
		B/F	10,647.36
	To Dismantle / Refit Trunk Compartment Boards & Trims		120.00 801
	To Supply End Panel Body Sealant		60.00 301n
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		60.00 ✓
	Labour Charge - Panel Beating, Repairing Of Rear Chassis, Inner Panel, Spare Tyre Panel etc. Cnt, Weld End Panel & Part Replacement		1,000.00 7501
	To Respray Affected Areas		1,000.00 8001
		Total :	<u>12,887.36</u>

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: