



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SKT 5312G

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	SCRATCHED	\$321.13	\$321.13
1	REAR BUMPER BRACKET RH	NOT NECESSARY	\$76.95	\$0.00
1	REAR BUMPER UPPER BRACKET RH	NOT NECESSARY	\$51.30	\$0.00
1	REAR BUMPER SIDE SEAL RH	NOT NECESSARY	\$59.85	\$0.00
1	REAR REFLECTOR RH	* CHECK	\$57.85	\$0.00
	LESS 25.00% DISCOUNT		(\$141.77)	(\$80.28)
			\$425.31	\$240.85
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NECESSARY	\$25.00	\$20.00
10	REAR BUMPER CLIPS @\$3.00 (SN)	NECESSARY	\$30.00	\$30.00
			\$55.00	\$50.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE AND REFITTING REAR BUMPER, REAR FENDER RH AND EACH OTHER		\$640.00	\$300.00
	SURFACE PREPARATION, SPRAY PAINT AND REAR BUMPER, REAR FENDER RH AND OTHER AFFECTED AREAS		\$500.00	\$400.00
	TO PERFORM DIAGNOSTIC CHECK	NOT NECESSARY	\$80.00	\$0.00
			\$1,220.00	\$700.00
GRAND TOTAL			\$1,700.31	\$990.85
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$43.39 NETT)			\$990.85
Report Ref No: CS/AGI24100282/Rnp3m4				

MRB

MOHAMMED RASUL BIN MOHD YUNUS



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.