

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24100284/TVP3M4**Date:** 08/11/2024REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No : SH8044D**Insured Vehicle No :** SMN3304B

Date of Loss: 15/10/2024

Nature of Claim: TP

Claim No: DMPC2401390H/02/ST

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SH8044D**

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)

Engine No: 2ZR2B96970

Reg. Date: 14/03/2019 (Man. Year: 2018)

Chassis No: JTDKB3FU503078951

Colour: Blue

Odometer: 673531 km

Engine Capacity: 1798 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size: 195/65R15

Front Left Side: West Lake 6 mm

Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,304.75	617.00	1,687.75	73.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,350.00	1,740.00	610.00	25.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,654.75	2,357.00	2,297.75	49.36
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	4,654.75	1,900.00	2,754.75	59.18
+ GST 9.00/9.00% (S\$)	418.93	171.00	247.93	59.18
Nett Amount (S\$)	5,073.68	2,071.00	3,002.68	59.18

INSPECTION

Date of Assignment: 16/10/2024

Date Inspected: 16/10/2024 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Nov 2024)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH8044D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR ASSY LH	Repair	1,258.30 FL	*- FL
2	1		*ROCKER PANEL GARNISH LH	Deformed	576.00 FL	*576.00 FL
3	1		*REAR FENDER LH	Repair	992.04 FL	*- FL
4	1		*REAR DOOR APPS LOGO	Cut	80.00 FS	*80.00 FS
5	1		*PATROL STICKER	Necessary	30.00 FS	*30.00 FS
6	1		*FRT COMFORT LOGO	Cut	75.00 FS	*75.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					3,011.34	761.00
- List Item Discount on L Items 25.00/25.00% (S\$)					706.59	144.00
Total Parts (S\$)					2,304.75	617.00
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	760.00
2	SPRAY PAINT	New	980.00	980.00
3	REMOVE / REFIX DOOR PARTS	New	120.00	0.00
4	TUFF KOTE	New	50.00	0.00
Gross Labour Cost (\$\$)			2,350.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >