



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2502305

INV Date 15/04/2025

Reference CD/LPC24100286/Rpa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SGZ 2892J
Insured Veh. GBH 6466J
Claim No. 24/24/24/VC05/030037
Policy No. Z24VC05025884
Accident Date 14/10/2024
Inspection Date 18/11/2024

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CD/LPC24100286/Rpa3q2(N)	
			Date: 15/04/2025	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBH 6466J	Veh. Inspected	SGZ 2892J
	Policy No.	Z24VC05025884	Coverage (\$)	0.00
	Claim No.	24/24/24/VC05/030037	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	18/11/2024
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ E200 AVG	c.c	1999
	Engine No.	HIDDEN	Year of Reg.	2024
	Chassis No.	W1K2140502A038723	Colour	BLACK
	Odometer	7383 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/45R19	CONTINENTAL	6 mm
	L/H Front Tyre	245/45R19	CONTINENTAL	6 mm
	R/H Rear Tyre	245/45R19	CONTINENTAL	6 mm
	L/H Rear Tyre	245/45R19	CONTINENTAL	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	14/10/2024	Inspection Date	18/11/2024
	Survey held at	CYCLE & CARRIAGE INDUSTRIES PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGZ 2892J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (SN)	TO REPAIR SEE LABOUR	1,731.05	-
1	RHF BASIC CARRIER, BUMPER (SN)	NOT NECESSARY	170.80	-
1	[STR] CUPPED BLIND RIVET (SN)	NOT NECESSARY	55.00	-
1	SUNDRIES (SN)	NECESSARY	15.00	15.00
			1,971.85	15.00
	<u>LABOUR</u>			
	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD.		380.00	380.00
	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		1,200.00	960.00
	RESPRAY ON FRONT BUMPER AND ACCIDENT AFFECTED AREA.		1,200.00	800.00
			2,780.00	2,140.00
GRAND TOTAL			4,751.85	2,155.00

RECOMMENDED COST OF REPAIRS			2,155.00
------------------------------------	--	--	-----------------

Report Ref No. CD/LPC24100286/Rpa3q2(N)

Market Value: \$239,000.00(est) less LTA Rebate: \$152,996.00(est) = Nett Value :\$86,004.00(est)

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SGZ 2892J



PHOTOGRAPHS FOR VEHICLE NO. : SGZ 2892J



PHOTOGRAPHS FOR VEHICLE NO. : SGZ 2892J




PHOTOGRAPHS FOR VEHICLE NO. : SGZ 2892J



PHOTOGRAPHS FOR VEHICLE NO. : SGZ 2892J



PHOTOGRAPHS FOR VEHICLE NO. : SGZ 2892J



PHOTOGRAPHS FOR VEHICLE NO. : SGZ 2892J



PHOTOGRAPHS FOR VEHICLE NO. : SGZ 2892J





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 9 of 9)

PHOTOGRAPHS FOR VEHICLE NO. : SGZ 2892J





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : SGZ 2892J

