


Company Reg No: 202136904Z

Tel : 6341 6789      Fax: 6341 6778  
E-mail:hdperfectautowork@gmail.com



DATE : 15.10.2024

|                  |   |                       |                    |
|------------------|---|-----------------------|--------------------|
| TO               | : | <b>INCOME</b>         | MOTOR CLAIMS DEPTS |
| VEHICLE NO       | : | <b>SMN4918Z</b>       |                    |
| MODEL            | : | <b>SEAT TOLEDO</b>    |                    |
| DATE OF ACCIDENT | : | <del>14.10.2024</del> | 15.10.24           |
| TIME OF ACCIDENT | : | 12:45 HOURS           |                    |

Veron

CLAIM DETAIL : PARTS

| S/N | DESCRIPTION                                     | QTY | UNIT LIST PRICE | TOTAL LIST PRICE       |
|-----|-------------------------------------------------|-----|-----------------|------------------------|
| 1   | FRONT BUMPER <i>Dished</i>                      | 1   | \$ 1,685.00     | \$ 1,685.00            |
| 2   | FRONT BUMPER TOWING COVER <i>Dished</i>         | 1   | \$ 45.00        | \$ 45.00               |
| 3   | FRONT BUMPER FOG LAMP <i>Smashed</i>            | 2   | \$ 586.00       | \$ <del>1,172.00</del> |
| 4   | FRONT BUMPER FOG LAMP COVER <i>Dished</i>       | 2   | \$ 486.00       | \$ <del>972.00</del>   |
| 5   | FRONT BUMPER LOWER GRILLE <i>crushed</i>        | 1   | \$ 384.00       | \$ <del>384.00</del>   |
| 6   | FRONT BUMPER INNER LOWER GARNISH <i>crushed</i> | 1   | \$ 364.00       | \$ 364.00              |
| 7   | FRONT BUMPER SIDE RETAINER <i>crushed</i>       | 2   | \$ 185.30       | \$ <del>370.60</del>   |
| 8   | FRONT BUMPER REINFORCEMENT <i>Dented</i>        | 1   | \$ 710.00       | \$ 710.00              |
| 9   | FRONT BUMPER SPONGE <i>crushed</i>              | 1   | \$ 488.00       | \$ <del>488.00</del>   |
| 10  | FRONT FENDER <i>Dished</i>                      | 2   | \$ 1,125.00     | \$ <del>2,250.00</del> |
| 11  | FRONT FENDER INNER COWLING <i>ton</i>           | 2   | \$ 389.60       | \$ <del>779.20</del>   |
| 12  | FRONT FENDER SUPPORT BRACKET RH <i>Probed</i>   | 1   | \$ 195.60       | \$ 195.60              |
| 13  | FRONT FENDER INNER SPONGE RH <i>ton</i>         | 1   | \$ 98.60        | \$ 98.60               |
| 14  | FRONT DOOR OUTER MOULDING RH <i>new</i>         | 1   | \$ 438.60       | \$ 438.60              |
| 15  | FRONT DOOR WEATHER STRIP RH <i>new</i>          | 1   | \$ 268.00       | \$ 268.00              |
| 16  | FRONT ROCKER PANEL RH <i>Buckled</i>            | 1   | \$ 895.60       | \$ 895.60              |
| 17  | FRONT DOOR PILLAR RH <i>Ry</i>                  | 1   | \$ 1,318.50     | \$ 1,318.50            |
| 18  | FRONT HEADLAMP <i>smashed</i>                   | 2   | \$ 1,842.00     | \$ 3,684.00            |
| 19  | FRONT HEADLAMP TOP PANEL <i>RH Dished</i>       | 2   | \$ 298.00       | \$ <del>596.00</del>   |
| 20  | FRONT HEADLAMP LOWER BRACKET RH <i>new</i>      | 1   | \$ 205.00       | \$ 205.00              |
| 21  | FRONT GRILLE C/W CHROME <i>crushed</i>          | 1   | \$ 782.00       | \$ 782.00              |

✓  
✓  
✓ 790  
✓ 490  
✓ 265  
✓ 210  
✓ 610  
✓ 225  
✓ 1890  
✓ 450  
—  
—  
+  
+  
✓  
+  
✓  
~~1/2~~ 298  
+  
✓

TO : INCOME MOTOR CLAIMS DEPTS  
 VEHICLE NO : SMN4918Z  
 MODEL : SEAT TOLEDO  
 DATE OF ACCIDENT : 14.10.2024  
 TIME OF ACCIDENT : 12:45 HOURS

|    |                                                 |   |    |          |    |                     |         |
|----|-------------------------------------------------|---|----|----------|----|---------------------|---------|
| 22 | FRONT GRILLE LOGO <i>new</i>                    | 1 | \$ | 96.00    | \$ | 96.00               | ✓       |
| 23 | BONNET <i>Dented</i>                            | 1 | \$ | 1,754.00 | \$ | 1,754.00            | ✓       |
| 24 | BONNET HINGE <i>new</i>                         | 2 | \$ | 86.00    | \$ | 172.00              | +       |
| 25 | BONNET INNER LOCK <i>new</i>                    | 1 | \$ | 320.00   | \$ | 320.00              | +       |
| 26 | BONNET INSULATOR <i>new</i>                     | 1 | \$ | 367.00   | \$ | 367.00              | +       |
| 27 | FRONT WIPER PANEL SIDE GARNISH <i>new</i>       | 2 | \$ | 105.60   | \$ | 211.20              | +       |
| 28 | FRONT SUPPORT PANEL <i>Crushed</i>              | 1 | \$ | 1,178.60 | \$ | <del>1,178.60</del> | ✓ 990   |
| 29 | FRONT SUPPORT PANEL TOP GARNISH <i>crushed</i>  | 1 | \$ | 186.00   | \$ | 186.00              | ✓       |
| 30 | FRONT WHEEL HOUSE PANEL RH <i>3 Repair</i>      | 1 | \$ | 1,755.00 | \$ | 1,755.00            | +       |
| 31 | FRONT WHEEL HOUSE TOP PANEL RH                  | 1 | \$ | 495.00   | \$ | 495.00              | +       |
| 32 | FRONT CHASSIS MEMBER RH <i>Repair</i>           | 1 | \$ | 986.20   | \$ | 986.20              | +       |
| 33 | FRONT AIR BAG (STEERING)                        | 1 | \$ | 2,764.00 | \$ | 2,764.00            | ✓       |
| 34 | FRONT AIR BAG (PASSENGER)                       | 1 | \$ | 1,910.00 | \$ | 1,910.00            | ✓       |
| 35 | FRONT AIR BAG IMPACT SENSOR <i>Adjusted</i>     | 2 | \$ | 352.00   | \$ | 704.00              | ✓       |
| 36 | FRONT AIR BAG MODULE SENSOR                     | 1 | \$ | 1,528.00 | \$ | <del>1,528.00</del> | ✓ 1215  |
| 37 | FRONT SAFETY BELT                               | 2 | \$ | 1,492.00 | \$ | <del>2,984.00</del> | ✓ 11820 |
| 38 | FRONT STEERING SPIRAL                           | 1 | \$ | 1,498.00 | \$ | <del>1,498.00</del> | ✓ 498   |
| 39 | HORN <i>new</i>                                 | 2 | \$ | 155.00   | \$ | 310.00              | +       |
| 40 | OUTSIDE TEMPERATURE SENSOR <i>new</i>           | 1 | \$ | 180.00   | \$ | 180.00              | +       |
| 41 | WATER COOLER <i>new crushed</i>                 | 1 | \$ | 368.00   | \$ | 368.00              | +       |
| 42 | AIR DUCT <i>new</i>                             | 1 | \$ | 193.00   | \$ | 193.00              | +       |
| 43 | RADIATOR <i>crushed</i>                         | 1 | \$ | 1,649.20 | \$ | 1,649.20            | ✓       |
| 44 | RADIATOR FAN COWLING <i>crushed</i>             | 1 | \$ | 487.20   | \$ | 487.20              | ✓       |
| 45 | RADIATOR FAN MOTOR <i>new</i>                   | 1 | \$ | 359.40   | \$ | 359.40              | +       |
| 46 | AIRCON CONDENSER SIDE AIR GUARD <i>RH Delo</i>  | 2 | \$ | 86.00    | \$ | <del>172.00</del>   | ✓ 2 86  |
| 47 | AIRCON CONDENSER <i>new</i>                     | 1 | \$ | 1,438.00 | \$ | 1,438.00            | +       |
| 48 | AIRCON PRESSURE PIPE <i>new</i>                 | 1 | \$ | 485.00   | \$ | 485.00              | +       |
| 49 | AIRCON SUCTION PIPE <i>not in</i>               | 1 | \$ | 455.00   | \$ | 455.00              | +       |
| 50 | FRONT WASHER TANK <i>crushed</i>                | 1 | \$ | 295.60   | \$ | 295.60              | ✓       |
| 51 | FRONT WASHER TANK MOTOR <i>new</i>              | 1 | \$ | 135.00   | \$ | 135.00              | +       |
| 52 | FRONT WASHER TANK MOTOR WIRE HARNESS <i>new</i> | 1 | \$ | 581.00   | \$ | 581.00              | +       |
| 53 | FRONT WASHER TANK TUBE <i>new</i>               | 1 | \$ | 285.00   | \$ | 285.00              | +       |
| 54 | FRONT LOWER ARM RH <i>Box</i>                   | 1 | \$ | 1,355.00 | \$ | <del>1,355.00</del> | ✓ 528   |
| 55 | FRONT KNUCKLE ARM RH <i>Dented</i>              | 1 | \$ | 876.20   | \$ | 876.20              | ✓       |

TO : INCOME MOTOR CLAIMS DEPTS  
 VEHICLE NO : SMN4918Z  
 MODEL : SEAT TOLEDO  
 DATE OF ACCIDENT : 14.10.2024  
 TIME OF ACCIDENT : 12:45 HOURS

|    |                                              |   |             |                        |           |
|----|----------------------------------------------|---|-------------|------------------------|-----------|
| 56 | FRONT SHOCK ABSORBER RH <i>Bent</i>          | 1 | 764.80      | \$ 764.80              | ✓         |
| 57 | FRONT WHEEL HUP RH <i>Dented</i>             | 1 | \$ 494.70   | \$ 494.70              | ✓         |
| 58 | FRONT WHEEL HUP BEARING RH <i>Bad</i>        | 1 | \$ 456.50   | \$ <del>456.50</del>   | ✓ 269.    |
| 59 | FRONT CROSS MEMBER <i>Bent</i>               | 1 | \$ 1,486.90 | \$ 1,486.90            | ✓         |
| 60 | FRONT DRIVE SHAFT RH <i>new</i>              | 1 | \$ 2,385.00 | \$ 2,385.00            | ✓ X       |
| 61 | FRONT LINKAGE RH <i>new</i>                  | 1 | \$ 185.00   | \$ 185.00              | ✓         |
| 62 | FRONT STEERING RACK AND PINION <i>Broken</i> | 1 | \$ 3,866.00 | \$ 3,866.00            | ✓         |
| 63 | FRONT WHEEL RIM <i>Dented</i>                | 1 | \$ 1,865.00 | \$ <del>1,865.00</del> | ✓ 680/sv) |

S/N: 680 35886-40  
 32297-76

TOTAL PRICE \$ 57,739.20  
 LESS 10% \$ 5,773.92  
 SUB TOTAL PRICE \$ 51,965.28

| S/N | DESCRIPTION                                           | QTY | UNIT S/NETT | TOTAL S/NETT         |       |
|-----|-------------------------------------------------------|-----|-------------|----------------------|-------|
| 1   | FRONT NUMBER PLATE <i>new</i>                         | 1   | \$ 80.00    | \$ 80.00             | ✓     |
| 2   | FRONT BUMPER CLIP (SET) <i>new</i>                    | 1   | \$ 80.00    | \$ <del>80.00</del>  | ✓ 30  |
| 3   | FRONT BUMPER LOWER GRILLE CLIP (SET)                  | 1   | \$ 80.00    | \$ 80.00             | ✓ 30  |
| 4   | FRONT BUMPER INNER LOWER GARNISH CLIP (SET)           | 1   | \$ 80.00    | \$ 80.00             | ✓ 30  |
| 5   | FRONT FENDER INNER COWLING CLIP (SET) <i>new</i>      | 1   | \$ 80.00    | \$ <del>80.00</del>  | ✓ 30  |
| 6   | BONNET SEALANT <i>new</i>                             | 1   | \$ 150.00   | \$ 150.00            | ✓     |
| 7   | BONNET INSULATOR CLIP (SET) <i>new</i>                | 1   | \$ 80.00    | \$ 80.00             | ✓     |
| 8   | FRONT SUPPORT PANEL TOP GARNISH CLIP (SET) <i>new</i> | 1   | \$ 60.00    | \$ <del>60.00</del>  | ✓ 20  |
| 9   | FRONT TYRE <i>Punctured</i>                           | 1   | \$ 300.00   | \$ <del>300.00</del> | ✓ 180 |
| 10  | ROCKER PANEL SEALANT <i>new</i>                       | 1   | \$ 100.00   | \$ <del>100.00</del> | ✓ 60  |
| 11  | FRONT WINDSCREEN SEALANT <i>new</i>                   | 1   | \$ 80.00    | \$ 80.00             | ✓     |
| 12  | FRONT WINDSCREEN INNER SHIELD <i>new</i>              | 1   | \$ 80.00    | \$ 80.00             | ✓     |
| 13  | RADIATOR COOLANT <i>new</i>                           | 1   | \$ 180.00   | \$ <del>180.00</del> | ✓ 50  |

430

TOTAL \$ 1,480.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

| S/N | JOB DESCRIPTION                            | PRICE       | ADJUSTED COST |
|-----|--------------------------------------------|-------------|---------------|
| 1   | PANEL BEATING, REMOVAL AND REPLACING PARTS | \$ 2,200.00 | 1200          |

TO : **INCOME** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SMN4918Z**  
 MODEL : **SEAT TOLEDO**  
 DATE OF ACCIDENT : 14.10.2024  
 TIME OF ACCIDENT : 12:45 HOURS

|    |                                                                                      |                        |      |
|----|--------------------------------------------------------------------------------------|------------------------|------|
| 2  | TO SPRAY PAINT AFFECTED AREA                                                         | \$ <del>2,000.00</del> | 1000 |
| 3  | TUFF COAT                                                                            | \$ <del>350.00</del>   | 100  |
| 4  | WIRING CHECK                                                                         | \$ <del>180.00</del>   | 30   |
| 5  | REMOVE AND REFIX CUSHION SEAT/<br>UPHOLSTRY AND ROOF LINNING TO<br>FACILITATE REPAIR | \$ <del>380.00</del>   | 60   |
| 6  | REFOCUS HEADLAMP BEAM                                                                | \$ 80.00               | +    |
| 7  | REMOVE AND REFIX FRONT WINDSCREEN                                                    | \$ 120.00              | +    |
| 8  | REMOVE, REFIX AND RESET AIRBAG                                                       | \$ <del>750.00</del>   | 350  |
| 9  | REMOVE AND REFIX FRONT UNDER<br>CARRIAGE                                             | \$ <del>650.00</del>   | 200  |
| 10 | REMOVE AND REFIX FRONT CROSS<br>MEMBER                                               | \$ <del>300.00</del>   | 150  |
| 11 | REMOVE AND REFIX STEERING RACK<br>AND PINION                                         | \$ <del>300.00</del>   | 120  |
| 12 | REMOVE AND REFIX FRONT DASHBOARD                                                     | \$ <del>650.00</del>   | 250  |
| 13 | FOUR WHEEL ALIGNMENT                                                                 | \$ <del>80.00</del>    | ✓    |
| 14 | REMOVE AND REFIX AIRCON<br>CONDENSOR AND REFILL AIRCON GAS                           | \$ <del>120.00</del>   | 60   |
| 15 | REMOVE AND REFIX RADIATOR AND<br>CONDUCT PRESSURE TEST                               | \$ <del>80.00</del>    | 60   |
| 16 | REMOVE AND REFIX WATER COOLER                                                        | \$ <del>80.00</del>    | 40   |

TO : INCOME MOTOR CLAIMS DEPTS  
VEHICLE NO : SMN4918Z  
MODEL : SEAT TOLEDO  
DATE OF ACCIDENT : 14.10.2024  
TIME OF ACCIDENT : 12:45 HOURS

|    |                                                                                                      |           |   |
|----|------------------------------------------------------------------------------------------------------|-----------|---|
| 17 | TO CHECK DIAGNOSTICS OF VEHICLE<br>MANAGEMENT/CONTROL UNITS, RESET<br>MEMORIES TO SPECIFICATION ETC. | \$ 650.00 | x |
|----|------------------------------------------------------------------------------------------------------|-----------|---|

3900

TOTAL \$ 8,970.00

TOTAL PARTS COST : \$ 53,445.28  
TOTAL LABOUR COST : \$ 8,970.00  
TOTAL REPAIR COST : \$ 62,415.28

Adrian L  
L/S 16/10/24

13 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE  
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED  
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.  
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

**IRENE**

SERVICE ADVISOR  
IRENE  
HP : 8297 9787

total: 37307.76

L/S: 29850

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: