

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

Hui Roy

ESTIMATE OF REPAIR

Veh# : SNN6521J

Model:

BYD E6

Accident Date : 13/10/2024

(20/12/2023 - 19/12/2023)

Location : SLE

3P:

FBE6925S (INCOME)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear door LH <i>Dented</i>	3762	4138.20	2550 ✓
2	1 pc	Rear door weatherstrip LH <i>new</i>		220.00	✓
3	1 pc	Rear door rubber stopper LH <i>new</i>		12.00	✓
4	1 pc	Rear door inner plastic seal cover LH <i>new</i>		30.00	✓
5	1 set	Rear door inner trim board clip LH <i>new</i>		50.00	✓
6	1 pc	Side skirt garnish LH <i>new</i>		310.20	✓
7	1 set	Side skirt garnish clip LH <i>new</i>		50.00	✓
		<i>2550</i> <i>3762</i> Sub-Total:	0.00	100.00	0.00
		<i>2655</i> <i>3385.80</i>	10%	0%	0%
		After Less %:	0.00	100.00	0.00
		Labour			
1		To remove & refix accident damaged parts & realign affected area.		400.00	300 ✓
2		To spray paint on accident affected area.		600.00	400 ✓
3		To remove & refix door mechanism. <i>760</i>		80.00	60 ✓
4		To rust proof affected area.		50.00	✓
		Sub-Total:		1,130.00	
		Total:		1,230.00	

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:
Date:



8778 1999
24 hr accident call



Adrian
1/10 16/10/24.

037uys.

total: 3115 (P/P)
4145.80 ✓