

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 14-Oct-24

INSURANCE: ECICS

MODEL: HYUNDAI IONIC

VEHICLE NO.: SH 7378 Y

Description	Qty	List Price	Amount
Front Bumper Cover <i>bt minority broken</i>	1	\$ 481.10	\$ 481.10
Front bumper top cover <i>HH</i>	1	\$ 476.30	\$ 476.30
Front Bumper Moulding Centre Upper <i>minority broken</i>	1	\$ 368.50	\$ 368.50
Front Bumper Bracket Top (LH) <i>HH</i>	1	\$ 35.00	\$ 35.00
Front Bumper Bracket (LH) <i>broken</i>	1	\$ 28.00	\$ 28.00
Front Bumper Retainer Mounting (LH) <i>HH</i>	1	\$ 65.30	\$ 65.30
Front Bumper Clips 10 pcs <i>HH</i>	1	\$ 25.00	\$ 25.00
Front Bumper Grille (LH) <i>damaged</i>	1	\$ 186.90	\$ 186.90
Front bumper air duct (LH) <i>HH</i>	1	\$ 153.80	\$ 153.80
Day Light ,LH <i>minority broken</i>	1	\$ 642.50	\$ 642.50
Headlamp Support Panel Assy <i>broken</i>	1	\$ 1,139.30	\$ 1,139.30
Headlamp(LH) <i>minority broken</i>	1	\$ 3,987.30	\$ 3,987.30
Frt Pillar Upper Cover - outer (LH) <i>damaged</i>	1	\$ 89.60	\$ 89.60
Front Fender(LH) <i>damaged</i>	1	\$ 490.70	\$ 490.70
Front Fender Apron Panel (LH) <i>HH</i>	1	\$ 756.20	\$ 756.20
Front Fender Apron Panel Upper(LH) <i>HH</i>	1	\$ 329.00	\$ 329.00
Front Fender Shield (LH) <i>damaged</i>	1	\$ 164.70	\$ 164.70
Frt Door(LH) <i>HH</i>	1	\$ 1,797.20	\$ 1,797.20
Frt Door Rubber <i>HH</i>	1	\$ 250.00	\$ 250.00
Front Door Regulator (LH) <i>broken</i>	1	\$ 750.40	\$ 750.40
Front Door Power Motor, LH <i>HH</i>	1	\$ 689.20	\$ 689.20
Front Door Hinge Upper (LH) <i>HH</i>	1	\$ 165.76	\$ 165.76
Front Door Hinge Lower (LH) <i>HH</i>	1	\$ 153.70	\$ 153.70
Front Door Check (LH) <i>HH</i>	1	\$ 72.98	\$ 72.98

✓
X
✓
X
✓
X
✓
✓
X
✓
✓
✓
X
X
✓
✓
X
X
✓
✓
X
X
✓
✓

Front Door Comfort Logo (LH) <i>HH</i>	SN	1	\$ 75.00	\$ 75.00
Front Windscreen Sealant <i>HH</i>	SN	1	\$ 46.00	\$ 46.00
Front Tyre(LH) <i>HH</i>	SN	1	\$ 216.00	\$ 216.00
SUB TOTAL				\$ 363.60
Labour Charge				
Panel Beating		1	\$2,000.00	\$2,000.00
Spray Painting Charge		1	\$1,600.00	\$1,600.00
Wiring Charge		1	\$100.00	\$100.00
Tuff Kote		1	\$100.00	\$100.00
Towing Charge		1	\$80.00	\$80.00
Transfer of Door Mechanism FRONT		1	\$80.00	\$80.00
Re-set Frt Power Window System		1	\$200.00	\$200.00
Four Wheel Alignment		1	\$120.00	\$120.00
Remove/Refix Undercarriage (Frt)		1	\$400.00	\$400.00
Remove/Refix Radiator		1	\$90.00	\$90.00
Remove/Refix Aircon & Refill Gas		1	\$130.00	\$130.00
Remove/Refix Front Windscreen Glass		1	\$120.00	\$120.00
Remove/Refix Dashboard		1	\$350.00	\$350.00
Diagnostic & Resetting To Erase Fault Code		1	\$550.00	\$550.00
TOTAL LABOUR				\$5,920.00
ESTIMATE TOTAL				\$ 33,520.59

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the Insurance Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

17/10/2024 @ 1030am

Not Author

2/Smr 9 days

[Signature]

2th Author

15,121.54

4/5 12,100/-

2030.00

75.00

900/-

800/-

30/-

30/-

HH

60/-

HH

60/-

150/-

HH

HH

HH

HH

HH