

ASS. REC. BY: Marcus

REF:

CS/INC 24100295/Uhh3**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

JQS3391

at Workshop m/s

Snofa

of

Insured:

SMM 67368

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value:

RM 2800

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

JQS3391

Yr Regn:

03/03/15Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kameho 135LC

c.c

135

Colour

White

A/C:

Insured / Std / NI / NA

Sp.Reading

41196

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

PMYU60410E0269969Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orstayedBrake: Inorder / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

70-90-17

R:

80-90-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

maxxis

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

14/09/24

D.O.I.

16/10/24

Survey held at

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop orO/S, N/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/10/24 1/s 900 ÷ 3.2 inbound under tree (Red, \$4882.10, 8490)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

)

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

NINC

Name : Sam Wee Kiong (88890648)

Accident Date : 14-Sep-24

Vehicle No : JQS3391 (DOR: 03-03-15)

Vehicle Model : Yamaha 135LC

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
2	Front fork tube assy	\$ 12 640.00 X
1	Fork under bracket	\$ 80 225.00 X
1	Front wheel rim	\$ 12 495.00 X
1	Front rim shaft	\$ 80 105.00 X
1	Front rim bearing	\$ 12 88.00 X
1	Front brake disc	\$ 12 185.00 X
1	Handle bar	\$ 12 145.00 X
1	Handle-bar ends (1 set)	38 \$ 12 125.00
1	Hand grip (1 set)	\$ 12 90.00 X
1	Handle bar inner bracket	\$ 12 135.00 X
1	Headlamp assy	350 \$ 12 485.00
1	Side mirrors (1 set)	68 \$ 12 110.00
1	Front signals (1 set)	\$ 80 140.00 X
1	Front signal lower garnish	\$ 12 105.00
1	Front side lower cover	\$ 12 125.00
1	Basket	\$ 12 125.00
1	Fairing assy (1 set)	520 \$ 12 650.00
1	Front footrest bracket	\$ 12 65.00
2	Front footrest rubbers	\$ 12 70.00
1	Gear pedal	\$ 80 125.00 X
1	Brake pedal	140 \$ 12 165.00
1	Rear handle	155 \$ 12 225.00
2	Rear footrests	\$ 80 80.00 X
2	Rear footrest brackets	\$ 80 156.00 X
		\$ 4,859.00
	Less 10%	\$ 485.90 X
		\$ 4,373.10

Special Net Items

1	Number plate (1 set)	\$ 12 38.00 20
2	Fork oils	\$ 12 30.00 X
2	Fork oil seals	\$ 12 56.00 X
1	Steering cone (1 set)	\$ 12 185.00 X
1	Sticket (1 set)	\$ 12 120.00 60
		\$ 429.00

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Name : Sam Wee Kiong (88890648)

Accident Date : 14-Sep-24

Vehicle No : JQS3391 (DOR: 03-03-15)

Vehicle Model : Yamaha 135LC

Estimated Repair Costs

<u>S/No.</u>	<u>Labour</u>	
1	To provide towing service (LOD) S\$40.00 <i>refer LOD</i>	\$ -
2	To check wiring and reset headlamp focusing	\$ 17 80.00 X
3	To provide labour	\$ 2 480.00 300
4	To re-align body frame	\$ 17 420.00 X
		\$ 980.00
Grand Total		\$ 5,782.10

Singapore Dollars: Five Thousand Seven Hundred Eighty-Two and Cents: Ten only



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: